

Maritec Tanker Management

Ship File No : N/A Office File No : N/A Form No : N/A Issue : N/A Revision : N/A Rev Date : N/A

Incident Report's Details

Vessel : Biskra Defect ID : 60 NCR # : 6/2021 Is NCR ? : Yes **Defect Details** DURING OUTBOUND PASSAGE AT ESCRAVOS CHANNEL ON 29.11.2021 AT 1412 HLT MT.BISKRA WAS GROUNDED AT THE POSITION LAT /LONG 05 Deg 31.84N ,005DEG 08.42E,VSL HDG: SPD AS VSL IN BALLAST CONDITION WITH DRAFT MAX 5.00M 29.11.2021/0918Hrs - Pob (Transit Buoy.23 to Escravos) 29.11.2021/1000Hrs - Anch aweigh, outbound 29.11.2021/1118Hrs - Anch, off Channel, Awaiting Inbound aground vessel MT Laprouse to clear channel 29.11.2021/1254Hrs - Anch aweigh (MT Laprouse cleared of channel) 29.11.2021/1340Hrs - Vessel entered the Bar, Buoy.14 (MT Oluwasen, 1st and MT Zeezee 2nd aground outbound) 29.11.2021/1412Hrs - Vessel touched bottom (Port side fwd bow) 2 outbound fwd of Biskra still aground, Biskra 3rd vessel aground 29.11.2021/1428Hrs - 2nd Outbound vessel MT.ZeeZee afloat and cleared channel 29.11.2021/1454Hrs - Ist Outbound MT Oluwasen afloat and cleared channel, Biskra afloat 29.11.2021/1512Hrs – Channel cleared of aground vessels, Underway outbound 29.11.2021/1530Hrs - River pilot away 29.11.2021/1536Hrs - Vessel crossed Bar 29.11.2021/1600Hrs - Cosp, Dep Sapele Requisition Code : Categories Primary : Incident Vessel Dept : Deck Inspector - Internal : Secondary : Improper tools Inspector External : Office Dept : Operations Inspection Date : Applicable Dates 29-Nov-2021 ETC: 02-Dec-2021 Date Completed : 02-Dec-2021 Date Raised : Other Details Priority : Normal Assigned By : Vessel Verified By : Nawin Khaware Display in Daily Meeting? : No SFI: Verified On : 14/Dec/2021 Causes NOTE - Today In & Out bound 5 vessels grounded. 3 Outbound vessels grounded at peak tide (Eventually all refloated and cleared) NOTE - The recent positioning of buoys reported inaccurate by pilots. NOTE - Vessel touched bottom at the normal route followed always while transiting. Escravos High water today- 1247Hrs LT. Vessel draft Aft – Less than 5.0 mtrs 2 VESSELS IN TRANSIT OUTBOUND FORWARD OF OUR VESSEL GOT AGROUND. VESSEL HAD ALREADY CROSSED POINT OF NO RETURN. **Corrective Action** VESSEL USED ASTERN MOVEMENT & BOW THRUSTER TO ALIGNED THE VESSEL OUTBOUND. WAITED FOR 2 OUTBOUND VESSELS TO REFLOAT. DE-BALLASTED & LIGHTERED THE VESSEL AROUND 10 CM'S. AS SOON AS CHANNEL WAS CLEAR VESSEL PROCEEDED OUTBOUND.

Preventive Action

VESSEL TO PREFERABLY BE THE FIRST VESSEL IN TRANSIT OR THE LAST VESSEL. VESSEL TO ADJUST ETA CROSSING BAR NOT BEFORE & AFTER 45 MINS OF PEAK TIDE.

Applicable Tags Descriptions Grounding Root Causes- Job Factor Others Root Causes- Personal Factor Improper Assessment Incorrect Information Direct Causes- Unsafe Conditions

Inadequate Warning System

Substandard Port and Berthing Facilities

Job Factors

Not Applicable

Personal Factors

Not Applicable

Follow Up On **Follow Up** By 14/Dec/2021 Nawin Khaware Basis submitted evidence, it's evident that Buoy marking in the channel was done wrongly which fails to offer safe passage to the vessel. Vessels were grounding every now and then due wrong marking of channel by the Harbour authority. Vessel didn't suffer any damage as incident was related to just touching the forward part on soft mud. We consider this report as closed now. Satyendra Kumar
 Staff Code -06/Dec/2021 This job was converted to a NCR on 06/Dec/21 10322 - 2/E EXPECTED COMPLETION DATE for this job has been 29/Nov/2021 Asfaha Tekeste changed from 01/Dec/2021 to 02/Dec/2021 Gebremichael
staff Code -10368 - MST **Before & After Pictures**

Before

After













| 0: AT | essel: M.T.BISKRA Date | | .11.2021 SI | Signature of Tested |
|-------|--|-----------------|-------------------------|----------------------|
| erial | Name | Rank | Result of Test (BAC) | Person |
| No. | (As in Passport) | MASTER | 0.0% | 17 |
| 1. | APANNA POODRIMADA | CH.OFF | 0.07. | J. |
| 2. | SAWANT AZHERUDDIN IQBAL | 2nd OFF | 0.01. | At |
| 3. | PLATICA CATALIN | CHENG | 0.0% | Chur |
| 4. | SUBASH CANDRA BOSE GANDHI | 3RD ENG | 0.0% | John |
| 5. | KALATHIPARAMBIL JOSEPH IMMANUEL | AB | 0.07. | 240 |
| 6. | AMAR SONKER | OILER | 0.0%. | de |
| 7. | | | | |
| 9. | | | | |
| 10. | | | | |
| 11. | | | | |
| 12 | | | | |
| 13. | | | | |
| 14 | | | | |
| 15 | | | | |
| 16 | | | | |
| 17 | | | | |
| 18 | | | | |
| 19 | | | | |
| 20 | | | | |
| 21 | l | | | IF |
| Test | Performed By: Rank - 2ND OFFIC | ER | Signature: | fit. |
| | Witnessed By: Rank MASTER | | Signature: | MASTER |
| lest | witnessed by. Rank - minstant. | | | M/T. BISKRA |
| Alcot | nol Testing Equipment : - | | - | WI/T. DISKINA |
| Make | : <u>ALCOHAWK</u> Model: <u>Slim</u> Dat | e Of Expiry Of | Shore Calibration: 04 | 4.04.2022 PANAMA |
| make | ALCOMANY | | | |
| NOT | This UNANNOUNCED Alcohol | Tant Chall Do (| Carried Out When As | ked For By Office |
| 1 | This UNANNOUNCED Alcohol When Master Is Being Tested, | Test Should Be | e Performed By Ano | ther Senior Officer, |
| | Preferably Chief Engineer. On Board Alcohol Test Is Also | | | |
| | Same Form Shall Be Used: - | Required to L | de carried out in r of | ioning en euliene |
| 3 | | | | |
| 3 | Post Incident, Disciplinary Situations Or | When Comeon | ale Behauler Cause | Concerns |

