

Maritec Tanker Management

Incident Reports Details

Ship File No: N/A Office File No: N/A Form No : N/A Issue : N/A Revision : N/A

: N/A

Rev Date

Vessel: Asphalt Teranga Defect ID: NCR #: 16/2023 Is NCR?: Yes

Defect Details

We have issue with HT Water pressure lost of Main Engine. During investigation we have found the attach pump got failure. Dismantle the pump for inspection and found the pump drive gear shaft worn out and gear got damaged. After open the crankcase inspection door, found water leaking from top of HT pump drive gear. Remove the blank and found very big hole on HT manifold.

Requisition Code:

Categories							
Primary :	Incident	Inspector - Internal :		Vessel Dept:	Engine		
Secondary :	Other	Inspector External :		Office Dept:	Technical		
		Inspection Date :					

Applicable Dates

Date Raised: 31-Jul-2023 ETC: 03-Aug-2023 Date Completed: 01-Aug-2023

Other Details						
Priority : Normal	Assigned By: Vessel	Verified By: Nawin Khaware				
Display in Daily Meeting? : No	SFI:	Verified On: 02/Aug/2023				

Causes

Mechanical Failure - Equipment breakdown - HT pump drive shaft and gear damaged

Corrective Action

Immediate action:

- 1.Reported to office & all relevant parties.
- 2.Notification made to nearest port control & VTS.3.Procedure followed for NUC (Not under command) as per ROR.

Planned action:

- 1.In coordination with office, Commenced preparing Towage operation to the port of Malaga. 2.Continuous monitoring of Set & drift and prepare the vessel for emergency anchoring.
- 3.To Open up Pump cover for further inspection and to establish the actual cause of damage.
- 4. Service Technician to be arranged for carrying out required repair.

Preventive Action

- 1.Increasing safety margin for inspection PMS routines for H/T cooling water system has been reduced from 12000 hours to 9000 hours to ensure required maintenance of cooling water pump has been carried out well before the recommended period of 12000 hours as advised by the manufacturer.
- 2. Routine maintenance of Cooling water system to be performed regularly under the strict supervision of C/E, Any abnormality identified during the course of inspection must be attended with great care.
- 3.Incident reports & learnings must be shared with the fleet vessels.

Applicable Tags

Descriptions

Machinery / Equipment Damage

Incident Reports Details Printed On: 02-Aug-2023 1/6

Root Causes- Job Factor

Excessive Wear and Tear

Root Causes- Management Factors

PMS Issue

Direct Causes- Unsafe Conditions

Defective Equipment, Machinery or Tools

Direct Causes- Unsafe Acts

Incorrect Use of Equipment or Machinery

Follow Up

On	Ву	Follow Up	
02/Aug/2023	Nawin Khaware	Repairs has been completed on 28th July/ and so finally she sailed out on 28th July/2300 LT. All system found running satisfactorily hence this incident could be considered as closed out now.	
02/Aug/2023	Nawin Khaware	ETC has been changed from "31 Jul 2023" to "03 Aug 2023".	

Before & After Pictures

Before



After

















File No. 2023/ACA/01/1115 File No. 2023/ACA/01/1115 File No. 2023/ACA/01/1115 File Panama NO No. 9263942 RIAN No. 103100 Job No. 8 First late of survey 20 Jul 2023 Date of Issue 28 Jul 2023 19:09 UTC-2 The surveyy detailed below have been carried out. It is recommended to the Society that the Ship's records be updated as follows. STATUTORY SURVEY ENDORSEMENT SHEET CERTIFICATES - None CERTIFICATES - None CERTIFICATES - None CERTIFICATES - None SOCIED ACTION F.O.L.8 Noted root dealt with RINA SERVICES S.p.A. SOCIED Speed Tymber Trus none 28 Jul 2023



Page 2 of 2

Incident Reports Details Printed On: 02-Aug-2023 4/6





Page 2 of 2

Printed On: 02-Aug-2023





