

Near Miss Details

Guidance: 01) Please do not mention any names in the near miss report. 02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet. 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.									
Vessel : Bahama Blue				Defect ID: 185					
Defect Details									
This is to report you that we found rope probably belong to fishing net which was observed floated on starboard side close to front of accommodation. Crew picked up the loose end of rope and tried to remove it but seems rope secured at bottom side by bottom anodes. Presently rope secured to deck. Planning to remove it by using work boat in next convenient port. Diameter of rope about 10 mm, loose end length about 5 meters. The distance from rope end to aft thrusters was about 10 m when loose rope was floating on water surface.									
Requisition Code :									
Categories									
Primary :	Near Miss		Vessel Dept:		Deck				
Secondary :	Other	Other		Office Dept :		Operations			
Applicable Dates									
Date Raised : 28-May-2023 Date Completed : 25-May-2023									
Other Details									
Priority :	Normal	QMS Elements Ref :		- SELECT -		Verified By :			
Show in Monthly Safety Meeting? :	No	SFI :				Verified On :			
Potential to become a serious accident : Medium Recurrence : Low									
Causes									
Vessel has fishing ropes stuck on the bottom anodes while sailing across coastal water full of fishing nets.									
Corrective Action									
One loose end of this fishing rope was connected with ship's messenger rope and secured on deck. At anchorage crew was using work boat pulling loose end of fishing rope with connected messenger into forward of vessel and put on mooring winch. Fishing rope was finally removed from bottom anode where it was stuck.									
Preventive Action									
Keep proper look-out to avoid area with fishing nets. Use search lights for obtaining look-ahead safety area clear of fishing nets.									
Applicable Tags									
Root Causes- Management Factors									
Problem Identification / Control Issue									

Root Causes- Personal Factor

Others

Direct Causes- Unsafe Conditions

Others

Substandard Acts

Other Unsafe Acts

Substandard Conditions

Ship Movement

Follow Up								
On	Ву	Follow Up						
28/May/2023	Valentin MITENKOV Staff Code - 10552 - MST	One loose end of this fishing rope was connected with ship's messenger rope and secured on deck. At anchorage crew was using work boat pulling loose end of fishing rope with connected messenger into forward of vessel and put on mooring winch. Fishing rope was finally removed from bottom anode where it was stuck.						

Before & After Pictures

