

Maritec Tanker Management

Defect List Details

Vessel : Bitu	Atlantic	Defect ID	: 74	NCR # :	5/2020	ls N	CR ? :	Yes
Defect Details								
14105 In pump room after opening the duct keel manhole observed a long piping system (port and starboard side of the tunnel) which goes longwise of the cargo tanks (aft to fore) and several flexible dirty by oil. This piping is not approved by Class or Flag Administration. According to Master of the ship, this piping system is used for heating the cargo by thermal oil. The ship was in loaded condition and it was impossible to enter in the tunnel due to high temperature. Further investigation to be carried out by Classification society.								
Requisition Code :								
Categories								
Primary :	Near Miss Inspe		tor - Internal:			Vessel Dept:	Engine	
Secondary :	Inadequte Engineering /Design	Inspec	tor External :	d :		Office Dept : Teo		ical
		Inspec	tion Date :					
Applicable Dates								
Date Raised :	Date Raised : 20-Mar-2020			ETC : 28-Mar-2020		Date Completed :		
Other Details								
Priority : Normal			Assigned By : Vessel			Verified By :		
Display in Daily Meeting? : No			SFI :			Verified On:		
Causes								
Due to ship converted from oil to bitumen product the stripping system in duct keel do not allow the flow of viscous cargo to the collecting point.								
Corrective Action								
Extra heating coils fabricated in shipyard and placed on board will be not used. Permanent approved installation is being arranged with RINA.								
Preventive Action								
Extra heating coils were fabricated in shipyard and placed on board. Permanent approved installation is being arranged with RINA.								
Applicable Tags								
Follow Up								
On	Ву		Follow Up					
21/Mar/2020	lar/2020 Rakesh Kumar Vessel Dept has b				een changed from "Engine" to "Deck".			
Before & After Pictures								