

## CCR. 7.2 (B) - TANK CONDITION REPORT - BALLAST / FRESH WATER TANKS

Date : 10/08/2018
Page : 1 of 3

Made by : QHSE
Approved by : MD
Rev. No : 0

Vessel: Bahama Blue	Location:	FDF Anchorage
Cargo Tank: _ BWT ZP	Insp Date:	16.01.2021

(Frequency: Ballast Tanks Bi-Annually, Fresh Water Tanks Annually)

## **General Condition:**

Coating: No	Yes		Type of (	Coating	: FPOXY
Date Last Coating Main	tenance	:	Full Re-coat Part Re-Coat Touch-up CHIPYAR D		
Tank Fitting & Equipment	Poor	Fair	Good	NA	Details Of Required / Attention
Hatch Coamings / Man hole covers					
Ladders / Steps / Handrails			₩/		
Level Gauge (Internal)					
Sounding Pipes & Striking Plate			V		
Internal Frames			U		
Valve Reach Rod				V	
Eductor Lines & Valves			V		
Line Supports & Piping Dressers			V		
Suction Well			V		
Bellmouth			V		
Hydraulic Lines & Valves			D		
Fixed Gas Detections Lines & Filters					
Ballast Line & Valves			Q		
Anodes (If Fitted)			Q		
Rust / Scale Formation				V	No Rust
Tank Bottom Coating			U		¥
Port Bulkhead Coating			V		
Starboard Bulkhead Coating			U		



## CCR. 7.2 (B) - TANK CONDITION REPORT - BALLAST / FRESH WATER TANKS

Date : 10/08/2018
Page : 2 of 3

Made by : QHSE
Approved by : MD

	1 de la				Rev. No : 0
For	ward Bulkhead Coating				
Aft	Bulkhead Coating		V		
Unc	ler-Deck / Tank Top		V		
Stri	ngers And Girders		D'		
Tar	k Vents		V		
Mu	d				MiNOR Mud
Ga	uge Glass –F <b>W</b> tanks			4	

Condition Of Tank Structure						
Describe Details Of Any Fractures, Substantial Corrosion, Localised Pitting, Buckling,						
Condition Of Coating (Good, Fair, Poor), Hard Rust, Areas of Penetrations, Leakage from Adjacent Compartments						
Good = Minor Spot Rust Only						
Fair = Local Breakdown Only						
Poor = General Breakdown or Hard Rust						
General Remarks / Action Required:						

**Chief Officer** 

efresh.

Master



## CCR. 7.2 (B) - TANK CONDITION REPORT - BALLAST / FRESH WATER TANKS

Date : 10/08/2018
Page : 3 of 3

Made by : QHSE

Approved by : MD Rev. No : 0

