

## CCR. 7.2 (B) - TANK CONDITION REPORT - BALLAST / FRESH WATER TANKS

Date : 10/08/2018
Page : 1 of 3

Made by : QHSE
Approved by : MD
Rev. No : 0

| Vessel: _ Bakan                      | ua Blue | Location: | FIST Anchorage |
|--------------------------------------|---------|-----------|----------------|
| <del>Cargo</del> Tank: _ <i>WβSY</i> | K41     |           | 14-5AN-2020    |

(Frequency: Ballast Tanks Bi-Annually, Fresh Water Tanks Annually)

### **General Condition:**

|                            | Coating : No   | Yes  | 4    | Type of  | Coating | Epoky                           |  |  |  |
|----------------------------|--|------|------|----------|---------|---------------------------------|--|--|--|
|                            | Date Last Coating Maintenance: Full Re-coat Part Re-Coat Touch-up SHIP |      |      |          |         |                                 |  |  |  |
| Tank Fitting & Equipment   |  | Poor | Fair | Good     | NA      | Details Of Required / Attention |  |  |  |
| Hatch Coam                 | ings / Man hole covers   |      |      | <b>D</b> |         |                                 |  |  |  |
| Ladders / Ste              | eps / Handrails  |      |      |          |         |                                 |  |  |  |
| Level Gauge                | (Internal)   |      |      |          | 12      |                                 |  |  |  |
| Sounding Pip               | oes & Striking Plate   |      |      | D        |         | 99                              |  |  |  |
| Internal Fran              | nes  |      |      | P        |         |                                 |  |  |  |
| Valve Reach                | Rod  |      |      |          | ₫/      |                                 |  |  |  |
| Eductor Line               | s & Valves   |      |      |          |         |                                 |  |  |  |
| Line Support               | s & Piping Dressers  |      |      |          |         |                                 |  |  |  |
| Suction Well               |  |      |      | 12       |         |                                 |  |  |  |
| Bellmouth                  |  |      |      | Tt/      |         |                                 |  |  |  |
| Hydraulic Lin              | es & Valves  |      |      | Ø        |         |                                 |  |  |  |
| Fixed Gas De               | etections Lines & Filters  |      |      |          |         |                                 |  |  |  |
| Ballast Line &             | & Valves   |      |      | <u>V</u> |         |                                 |  |  |  |
| Anodes (If Fit             | tted)  |      |      | V        |         |                                 |  |  |  |
| Rust / Scale I             | Formation  |      |      |          | W       | No zust                         |  |  |  |
| Tank Bottom                | Coating  |      |      | <b>V</b> |         |                                 |  |  |  |
| Port Bulkhea               | d Coating  |      |      | U        |         |                                 |  |  |  |
| Starboard Bulkhead Coating |  |      |      | K        |         |                                 |  |  |  |



### CCR. 7.2 (B) - TANK CONDITION REPORT - BALLAST / FRESH WATER TANKS

Date : 10/08/2018
Page : 2 of 3

Made by : QHSE
Approved by : MD

| - International Control of the Contr | - | <br> |                    | Rev. No . 0 |
|--|---|------|--------------------|-------------|
| Forward Bulkhead Coating   |   | 107  |                    |             |
| Aft Bulkhead Coating   |   | U    |                    |             |
| Under-Deck / Tank Top  |   |      |                    |             |
| Stringers And Girders  |   |      |                    |             |
| Tank Vents   |   | U    |                    |             |
| Mud  |   |      | \(\overline{\pi}\) | No mud      |
| Gauge Glass –FW tanks  |   |      | 山                  |             |
|  |   |      |                    |             |

#### **Condition Of Tank Structure**

Describe Details Of Any Fractures, Substantial Corrosion, Localised Pitting, Buckling, Condition Of Coating (Good, Fair, Poor), Hard Rust, Areas of Penetrations, Leakage from Adjacent Compartments

Good = Minor Spot Rust Only
Fair = Local Breakdown Only
Poor = General Breakdown or Hard Rust

General Remarks / Action Required:

PIEF OFFICER

Master



# CCR. 7.2 (B) - TANK CONDITION REPORT - BALLAST / FRESH WATER TANKS

Date : 10/08/2018
Page : 3 of 3

Made by : QHSE
Approved by : MD
Rev. No : 0

