

CCR. 7.2 (B) - TANK CONDITION REPORT - BALLAST / FRESH WATER TANKS

Date : 10/08/2018 Page : 1 of 3 Made by : QHSE Approved by : MD Rev. No : 0

Vessel: _ Bahama Blue	Location: FDF Anchorage
-Cargo Tank:	Insp Date: 15-SAN-2021

(Frequency: Ballast Tanks Bi-Annually, Fresh Water Tanks Annually)

Gene	eral Condition:					
	Coating: No	Yes	b	Type of (Coating	: EPOXY
	Date Last Coating Maint	enance	:	Full Re-	-coat 🗌	Part Re-Coat Touch-up SHIPYARD NEW BUILDER 2018
Tank Fitting & Equipment Po		Poor	Fair	Good	NA	Details Of Required / Attention
Hatch Coamin	gs / Man hole covers					
Ladders / Step	os / Handrails					
Level Gauge ((Internal)				V	
Sounding Pipe	es & Striking Plate					
Internal Frame	es			TT/		
Valve Reach I	Rod					
Eductor Lines	& Valves					
Line Supports	& Piping Dressers					
Suction Well				U		
Bellmouth				Ŭ		
Hydraulic Line	es & Valves					
Fixed Gas De	tections Lines & Filters				V	
Ballast Line &	Valves					
Anodes (If Fit	ted)					
Rust / Scale F	Formation				W	No Rust
Tank Bottom	Coating					
Port Bulkhead	d Coating			Q/		
Starboard Bu	lkhead Coating			4		



CCR. 7.2 (B) - TANK CONDITION REPORT - BALLAST / FRESH WATER TANKS

Date : 10/08/2018
Page : 2 of 3

Made by : QHSE
Approved by : MD
Rev. No : 0

	U		
	4		
	W		
	t		
		0	it mud
		U	
	t.c.		

Condition Of Tank Structure
Describe Details Of Any Fractures, Substantial Corrosion, Localised Pitting, Buckling,
Condition Of Coating (Good, Fair, Poor), Hard Rust, Areas of Penetrations, Leakage from Adjacent Compartment
Good = Minor Spot Rust Only
air = Local Breakdown Only
Poor = General Breakdown or Hard Rust
General Remarks / Action Required:

Chief Officer

eloh-

Master



CCR. 7.2 (B) - TANK CONDITION REPORT - BALLAST / FRESH WATER TANKS

Date : 10/08/2018 Page : 3 of 3

Made by : QHSE Approved by : MD Rev. No : 0

