

Vessel:

BITU ATLANTIC

CCR. 7.2 (B) - TANK CONDITION REPORT - BALLAST / FRESH WATER TANKS

Location:

Date : 10/08/2018 Page : 1 of 3 Made by : QHSE

Approved by ; MD Rev. No : 0

Cargo Tank:	<u>ibt</u>	_			Insp Date: 28/09/218
(Frequency : Ballast Tanks 8)	-Annual	lγ, Fres	h Water	Tanks /	Annualiy)
General Condition: 54	lister	4			
Coating: No	Yes	V	Type of	Coating	E EPOXY
Date Last Coating Main	tenance);	Full Re	-coat [Part Re-Coat Touch-up 27/09/2/2
Tank Fitting & Equipment	Poor	Fair	Good	NA	Details Of Required / Attention
Hatch Coamings / Man hole covers			Ø		
Ladders / Steps / Handrails					
Level Gauge (Internal)			Ø		
Sounding Pipes & Striking Plate			Ø		:
Internal Frames			Ø		
Valve Reach Rod				Ø	
Eductor Lines & Valves					ulv inorder pripeturonel
Line Supports & Piping Dressers				Ø	
Suction Well				\square	
Beilmouth			M		
Hydraulic Lines & Valves				Ø	
Fixed Gas Detections Lines & Filters					
Ballast Line & Valves				Ø	ulv inside pipe tunne)
Anodes (if Fitted)					
Rust / Scale Formation			Ø		
Tank Bottom Coating			Ø		
Port Bulkhead Coating			Ø		·
Starboard Bulkhead Coating			Ø		



CCR. 7.2 (B) - TANK CONDITION REPORT - BALLAST Made by

Date : 10/08/2018 Page : 2 of 3

Made by : QHSE Approved by : MD

	 -	· · · · · · · · · · · · · · · · · · ·			Rev. No : 0
Forward Bulkhead Coating					-
Aft Bulkhead Coating			V		
Under-Dack / Tank Top			Ø		
Stringers And Girders			Ø		
Tank Vents			Ø		
Mud			Ø		
Gauge Glass –FW tanks				Ø	
m					

Condition Of Tank Structure Describe Details Of Any Fractures, Substantial Corrosion, Localised Pitting, Buckling, Condition Of Coating (Good, Fair, Poor), Hard Rust, Areas of Penetrations, Leakage from Adjacent Compartments Sood = Minor Spot Rust Only Seir = Local Breakdown Only								
Poor = General Br		Hard Rust						
General Remarks	/ Action Requ	uired:			-			
lv B T Present	wes	sport c	h. p. bud/ Jamb	Panited Very g	dung	4/4	peuson	

Chief Officer


Master

This form is to be completed in conjunction with CCR 7.0 / CCR 7.1 and forwarded by Email and filed as hard copy on board in CCR 7.2 folder



Date : 10/08/2018
Page : 3 of 3

Made by : QHSE
Approved by : MD
Rev. No : 0





CCR. 7.2 (B) - TANK CONDITION REPORT - BALLAST /FRESH WATER TANKS

Date : 10/08/2018 : 1 of 3 Page Made by QHSE Approved by : MD Rev. No. : 0

Vessel: _ BITN ATLANTIC					Loc	ation: <u>Co</u>	co shipperd
Carg	go Tank: <u>5°S</u>	<u> </u>	_			Insp Date:	11/09/2018
(Fre	quencγ : Ballast Tanks ΒΙ	-Annua	lly, Fres	h Water	Tanks A	nnually)	
Gen	eral Condition: $\int \omega dz$	spark	boy				
	Coating: No	Yes	V	-	Coating:		
	Date Last Coating Main	tenance	9:	Full Re	-coat 🗍	Part Re-Coat ☐	Touch-up 2 10 09 23 18
Tank Fit	tting & Equipment	Poor	Fair	Good	NA	Details C	of Required / Attention
Hatch Coami	ngs / Man hole covers					<u>.</u>	<u> </u>
Ladders / Ste	ps / Handrails						
Level Gauge	(Internal)			Ø		· ·	
Sounding Pip	es & Striking Plate			Ø			
Internal Fram	o s 			Q/		****	
Valve Reach	Rod						-
Eductor Lines	& Valves				Image: second control of the control		10
Line Supports	& Piping Dressers				Ø		
Suction Well	***						
Belimouth				D			
Hydraulic Line	es & Valves						V
Fixed Gas De	tections Lines & Filters						·
Ballast Line &	Valves						
Anodes (If Fitt	ed)			Ø		<u></u>	
Rust / Scale F	ormation						114
Tank Bottom (Coating			团			
Port Buikhead	Coating			Ø			
Starboard Bull	khead Coating			Ø			



Date : 10/08/2018 Page : 2 of 3 Made by : QHSE

Approved by : MD

SATIMENTAL MARKET SATI	,				Rev. No : 0
Forward Bulkhead Coaling			Ø		
Aft Bulkhead Coating			Ø		
Under-Deck / Tank Top			Ø		
Stringers And Girders			Z		
Tank Vents			Ø		
Mud			Ø		
Gauge Glass –FW tanks				Ø	
					·

Candition Of T	ank Structure

Describe Details Of Any Fractures, Substantial Corrosion, Localised Pitting, Buckling, Condition Of Coating (Good, Fair, Poor), Hard Rust, Areas of Penetrations, Leakage from Adjacent Compartments

Good = Minor Spet Rust Only Fair = Local Breakdown Only

Poor = General Breakdown or Hard Rust

General Remarks / Action Required:

WBF was spot shipped / Pavided dwing obuydoch. Bresent condition of Lamb & very good.

Chief Officer

Maste

This form is to be completed in conjunction with CCR 7.0 / CCR 7.1 and forwarded by Email and filed as hard copy on board in CCR 7.2 folder




 Date
 : 10/08/2018

 Page
 : 3 of 3

 Made by
 : QHSE

Approved by : MD Rev. No : 0





CCR. 7.2 (B) - TANK CONDITION REPORT - BALLAST / FRESH WATER TANKS

Date : 10/08/2018 Page : 1 of 3 : QHSE

Made by Approved by : MD Rev. No : 0

Vessel: _ BITU ATLANTIC					Lo	Insp Date: 04/09/2016			
Cargo Tank: <u>& P B NB T</u>						Insp Date: 04/09/2016			
(Fre	quency : Ballast Tanks Bi	-Annuai	ly, Fres	h Water	Tanks				
General Condition: Solis July									
	Coating: No	Yes	Z	Type of	Coating	B: EPORY			
	Date Last Coating Main	tenance	l:	Fuli Re	-coat [Part Re-Coat ☐ Touch-up ☑ 02/09/2-16			
Tank Fi	tting & Equipment	Poor	Fair	Good	NA	Details Of Required / Attention			
Hatch Coami	ngs / Man hole covers								
Ladders / Ste	ps / Handrails								
Level Gauge	(Internal)			Ø					
Sounding Pip	es & Striking Plate								
Internal Fram	es			Ø					
Valve Reach	Rod				Ŋ				
Eductor Lines	& Valves				Ø	VIV inside pipe tunnel			
Line Supports	s & Piping Dressers				Q				
Suction Well	·				Ø				
Bellmouth				D					
Hydraulic Line	es & Valves				Ø				
Fixed Gas De	tections Lines & Filters			Ø					
Ballast Line &	Valves				Ø	VIV inside pipe tunnel			
Anodes (If Fit	ted)			Ø					
Rust / Scale F	ormation			Ø					
Tank Bottom	Coating			Ø					
Port Bulkhead	l Coating			Ø					
Starboard But	khead Coating								



Date : 10/08/2018 Page : 2 of 3

Made by QHSE Approved by : MD

SANSAN WYNKERWEIG, J	, . <u></u>		,			Rev. No	: 0	1
Forward Bulkhead Coating			Ø					
Aft Bulkhead Coating			Ø			<u>'</u>		
Under-Deck / Tank Top			ď		"	· <u> </u>		
Stringers And Girders			Ø			, <u>-</u>		·-·
Tank Vents			Q			•	., <u></u> .	· · · <u>-</u> · ·
Mud			Ø				<u>-</u>	,
Gauge Glass –FW tanks				Ø				·
		·	-1			_ '		

Condition Of Tank Structure	
Describe Details Of Any Fractures, Substantial Corrosion, Localised Pitting, Buckling,	
Condition Of Coating (Good, Pair, Poor), Hard Rust, Areas of Penetrations, Leakage from Adjacent Compartment	ts

Good = Minor Spot Rust Only Fair = Local Breakdown Only Poor = General Breakdown or Hard Rust

General Remarks / Action Required:

WET were spot shipped / Pander duny 5/4 person.
Present condition of Land very good


Chief Officer

This form is to be completed in conjunction with CCR 7.0 / CCR 7.1 and forwarded by Email and filed as hard copy on board in CCR 7.2 folder



Date : 10/08/2018
Page : 3 of 3

Made by : QHSE
Approved by : MD
Rev. No : 0





Vessel: BITO ATUANTIC

CCR. 7.2 (B) - TANK CONDITION REPORT - BALLAST / FRESH WATER TANKS

Location:

Date : 10/08/2018
Page : 1 of 3
Made by : QHSE
Approved by : MD

Rev. No

Cosco Shipyard

Car	go Tank: <u>65 P</u>	abr	-			Insp Date: 10 /0 9/20) f
(Fre	equency : Ballast Tanks B	l-Annua	lly, Fres	h Water	Tanks	Annual(y)
Ger	eral Condition: .S	"alist	· Jug			
,,,,,	Coating : No	Yes	d	Type of	Coatin	& EPOXY
- <u>-</u> -	Date Last Coating Main	tenance	::	Full Re	-coat [☐ Part Re-Coat ☐ Touch-up ☐ 0-8 0-9 1-1
Tank Fi	tting & Equipment	Poor	Fair	Good	NA	Details Of Required / Attention
Hatch Coami	ings / Man hole covers			Ø		
Ladders / Ste	eps / Handrails			12		
Level Gauge	(internal)			Ø		
Sounding Plp	es & Striking Plate			Ø		
Internal Fram	ies			Ø		
Valve Reach	Rod				Ø	
Eductor Lines	s & Valves					vlv incide pipe tunnel
Line Supports	s & Piping Dressers				Ø	
Suction Well					K	
Bellmouth	<u> </u>			Ø		
Hydraulic Line	es & Vaives				Ū∕	
Fixed Gas De	tections Lines & Filters					· · · · · · · · · · · · · · · · · · ·
Bailast Line &	Valves				Ø	V/V inside pipe Avanel
Anodes (# Fit	ted)					
Rust / Scale F	ormation			Ø		
Tank Bottom	Coating			Ø		
Port Bulkhead	i Coating			d		
Starboard But	khead Coating			Ø		



Date : 10/08/2018 Page : 2 of 3 Made by : QHSE

Approved by : MD

 	 _			Nev. No ; 0
Forward Bulkhead Coating		g		
Aft.Bulkhead Coating		Q		
Under-Deck / Tank Top		Ø		
Stringers And Girders		Ø		
Tank Vents		V		
Mud		Ø		
Gauge Glass –FW tanks			Ø	

Condition	Of Tank Structure

Describe Details Of Any Fractures, Substantial Corrosion, Localised Pitting, Buckling, Condition Of Coating (Good, Fair, Poor), Hard Rust, Areas of Penetrations, Leakage from Adjacent Compartments

Good = Minor Spot Rust Only

Fair = Local Breakdown Only

Poor = General Breakdown or Hard Rust

General Remarks / Action Required:

WET was spot chipber | Panted duny Shippard. Preser Could to of sands very good

Chlef Officer

This form is to be completed in conjunction with CCR 7.0 / CCR 7.1 and forwarded by Email and filed as hard copy on board in CCR 7.2 folder



Date : 10/08/2018
Page : 3 of 3
Made by : QHSE

Approved by : MD Rev. No 0

