

Vessel: _ BITUAILANTIC

CCR. 7.2 (B) - TANK CONDITION REPORT - BALLAST / FRESH WATER TANKS

Location:

Date : 10/08/2018
Page : 1 of 3
Made by : QHSE

Made by : QHSE Approved by : MD Rev. No : 0

COSO SHIPPALD

BT	-			Insp Date: 02/09/2015
Annual	y, Fres	h Water	Tanks A	Annually)
v. J	ely			
Yes			-	
tenance	:	Full Re	-coat	Part Re-Coat Touch-up 1 . 8//09/2010
Poor	Fair	Good	NΑ	Details Of Required / Attention
				····
				4
			QZ	
			Ø	VIV wasde Pipe turnel.
			W	
			V	VIV worth like dunn!
		الما		
		Q/		
	Annual Yes tenance Poor	Annually, Fres Yes Poor Fair O O O O O O O O O O O O O O O O O O O	Annually, Fresh Water Yes Type of tenance: Full Re Poor Fair Good O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O O	Annually, Fresh Water Tanks A Yes Y Type of Coating Tenance: Full Re-coat Poor Fair Good NA O O O O O O O O O O O O O O O O O O O O O



Date : 10/08/2018 Page : 2 of 3 Made by : QHSE

Approved by : MD

					J Kev. No	. 0	[
Forward Bulkhead Coating							•
Aft Bulkhead Coating		Ū′				***************************************	,
Under-Deck / Tank Top							
Stringers And Girders		W					· · ·
Tank Vents		Ø					
Mud		□Z′					
Gauge Glass –FW tenks			<u> </u>	· .			

Conditi	ion Ol	Tank	Struc	ture

Describe Details Of Any Fractures, Substantial Corrosion, Localised Pitting, Buckling, Condition Of Coating (Good, Fair, Poor), Hard Rust, Areas of Penetrations, Leakage from Adjacent Compartments

Good = Minor Spot Rust Only

Fair = Local Breakdown Only

Poor = General Breakdown or Hard Rust

General Remarks / Action Required:

WET were spot chipder / Panter duny Shippanel perior
Condition of coding very Good:


Chief Officer

This form is to be completed in conjunction with CCR 7.0 / CCR 7.1 and forwarded by Email and filed as hard copy on board in CCR 7.2 folder



Date : 10/08/2018 Page : 3 of 3 Made by : QHSE

Approved by : MD Rev. No : 0





ST Date : 10/08/2018
Page : 1 of 3

Made by : QHSE
Approved by : MD
Rev. No : 0

Vessel: BITU ATLANTIC	Location: losco Shipyand
Cargo Tank:	location: Losco Shipyard Insp Date: 11/09/18

(Frequency: Ballast Tanks Bi-Annually, Fresh Water Tanks Annually)

General Condition:

	Coating: No	Yes	d	Type of	Coatin	B: EPOXY			
	Date Last Coating Main	tenance	::	Full Re	Full Re-coat Part Re-Coat Touch-up 10 09 20				
₹ank F	tting & Equipment	Poor	Fair	Good	NA	Details Of Required / Attention			
Hatch Coami	ngs / Man hole covers			Ø		· · · · · · · · · · · · · · · · · · ·			
Ladders / Ste	eps / Handralis			Ø					
Level Gauge	(Internat)			Ø					
Sounding Pip	es & Striking Plate			Ø					
Internal Fram	es			Ø		· · · · · · · · · · · · · · · · · · ·			
Valve Reach	Rod				Ø				
Eductor Lines	s & Valves				Q	vlu inside pipe dunnel			
Line Supports	s & Piping Dressers				ष्				
Suction Well									
Belimouth				Ø					
Hydraulic Line	es & Valves				Ø				
Fixed Gas De	tections Lines & Filters					· · · · · · · · · · · · · · · · · · ·			
Ballast Line &	Valves				Z	VIV ihade pipe tunnel			
Anodes (if Fig	ted)					, <u> </u>			
Rust / Scale f	ormation			1					
Tank Bottom	Coating			ď					
Port Bulkhead	l Coating			Ø		VALUE			
Starboard Bul	khead Coating			Ø					



Date : 10/08/2018 Page : 2 of 3 Made by : QHSE

ASSAMILATION CO.	 				Rev. No	:0	- (
Forward Bulkhead Coating		Ø			<u></u>		
Aft Bulkhead Coating							
Under-Deck / Tank Top							
Stringers And Girders		Ø		_		-	
Tank Vents		12/			- -		
Mud		Ø					
Gauge Glass –FW tanks			d	<u> </u>			· ·
							

Condition		-
I ONAIMAN	(III Janb	Circumstana
VVIIMILIANI	VI IOIN	.341 111.411.1

Describe Details Of Any Fractures, Substantial Corrosion, Localised Pitting, Buckling, Condition Of Coating (Good, Fair, Poor), Hard Rust, Areas of Penetrations, Leakage from Adjacent Compartments

Good = Minor Spot Rust Only Fair = Local Breakdown Only

Poor = General Breakdown or Hard Rust

General Remarks / Action Regulred:

WBT was spot chipped / Parited duny 5/4. Present tanh condition very Goods

Chief Officer


Master

Ļ

This formula to be completed in conjunction with CCR 7.0 / CCR 7.1 and forwarded by Email and filed as hard copy on board in CCR 7.2 folder



Date : 10/08/2018
Page : 3 of 3
Made by : QHSE
Approved by : MD
Rev. No : 0





Tank Bottom Coating

Port Bulkhead Coating

Starboard Bulkhead Coating

CCR. 7.2 (8) - TANK CONDITION REPORT - BALLAST / FRESH WATER TANKS

Date : 10/08/2018
Page : 1 of 3

Made by : QHSE
Approved by : MD
Rev. No : 0

Vessel: <u>BITU ATLANT</u> IC					Ło	cation: Cora Mipyard		
Carp	Cargo Tank:					insp Date: 0.3/0.9/2018		
(Fre	quency : Ballast Tanks Bi	-Annuai	ly, Fres	h Water	Tanks a			
Gen	eral Condition: Scl	rsfet						
	Coating: No	Yes	d	Type of	Coating	EPONY		
Date Last Coating Maintenance: Full Re-coat Part Re-Coat Touch-up 2/09/								
Tank Fi	tting & Equipment	Poor	Fair	Good	NA	Details Of Required / Attention		
Hatch Coami	ngs / Man hole covers			Ø				
Ladders / Ste	ps / Handralls							
Level Gauge	(Internal)			Ø				
Sounding Plp	es & Striking Plate			Ø				
Internal Fram	es			Ø		,		
Valve Reach	Rod				Ø			
Eductor Lines	s & Valves				Ø	V/v Inside lipe tunnel		
Line Supports	s & Piping Dressers				Ø			
Suction Well					Ø			
Bellmouth				Ø				
Hydraulic Line	es & Valves				Ø			
Fixed Gas De	etections Lines & Fliters			Z				
Ballast Line &	Valves				Ø	VIV inside Pipe tunnel		
Anodes (If Fit	ted)			Ø				
Rust / Scale f	Formation			Ø				
			· -	, ,				



Date : 10/08/2018 Page : 2 of 3 Made by : QHSE

Approved by : MD

Forward Bulkhead Coating	
Aft Bulkhead Coating	
Under-Deck / Tank Top	
Stringers And Girders	<u></u>
Tank Vents	
Mud	· · · · · · · · · · · · · · · · · · ·
Gauge Glass –FW tanks	

Condition Of Tank Structure Describe Details Of Any Fractures, Substantial Corrosion, Localised Pitting, Buckling, Condition Of Coating (Good, Fair, Poor), Hard Rust, Areas of Penetrations, Leakage from Adjacent Compartments						
Good = Minor S Fair = Local Brea Poor = General I	kdown Only			•		
General Remark	s / Action Re	quired:				
WRT Buses	were -	spot chiff	ed I lamited dung	S/y person		

Chief Officer


Master

This form is to be completed in conjunction with CCR 7.0 / CCR 7.1 and forwarded by Email and filed as hard copy on board in ECR 7.2 folder



Date : 10/08/2018 Page : 3 of 3 Made by : QHSE

Approved by : MD Rev. No : 0





Vessel: _ BITO ATLANTIC

Cargo Tank: <u>& ま いおり</u>

CCR. 7.2 (B) - TANK CONDITION REPORT ~ BALLAST FRESH WATER TANKS

Location:

Date : 10/08/2018 Page : 1 of 3 Made by GHSE Approved by : MD Rev. No : 0

Can	go Tank: _ <u>광호</u>	WBT	_			Insp Date: 12/09/2018
(Fre	quency : Ballast Tanks B	i-Annual	lly, Fres	h Water	Tanks	Annualty)
Gen	neral Condition: Sal	Jau	day			
	Coating: No	Yes		Type of	Coatin	8: EPOXY
	Date Last Coating Main	tenance	1:	Full Re	-coat [☐ Part Re-Coat ☐ Touch-up ☐ 10/09/2018
Tank Fi	tting & Equipment	Poor	Fair	Good	ΝA	Details Of Required / Attention
Hatch Coami	ings / Man hole covers			M		
Ladders / Ste	eps / Handrails			M		
Level Gauge	(Internal)					<u> </u>
Sounding Pip	es & Striking Plate					
Internal Fram	es			Ø		
Valve Reach	Rod				Ø	
Eductor Lines	& Valves				Ø	VIV inside pipe funnel
Line Supports	& Piping Dressers				Ď	
Suction Well					Q	
Bellmouth				Ø		
Hydraullo Line	es & Valves				๔	
Fixed Gas De	tections Lines & Filters					
Ballast Line &	Valves				Ø	vlv inside lipe tunnel
Anodes (If Fit	ted)					1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
Rust / Scale F	ormation					
Tank Bottom	Coating			\square		T
Port Bulkhead	l Coating			Ø		
Starboard But	khead Coating					



Date : 10/08/2018
Page : 2 of 3

Made by : QHSE
Approved by : MD

	 			Rev. No : 0
Forward Bulkhead Coating				
Aft Bulkhead Coating		d		
Under-Deck / Tank Top		Ø		
Stringers And Girders		Ø		
Tank Vents		Ø		
Mud		Ø		
Gauge Glass –FW tanks			Ø	
7				

Condition Of Tank Structure Describe Details Of Any Fractures, Substantial Corrosion, Localised Pitting, Buckling, Condition Of Coating (Good, Fair, Poor), Hard Rust, Areas of Penetrations, Leakage from Adjacent Compartments	
Good = Minor Spot Rust Only Fair = Local Breakdown Only Poor = General Breakdown or Hard Rust	
General Remarks / Action Required:	
WBT was spot dipped I aimed dung dry doch Peresert Condition of Janh. very good	

Chief Officer

Master

This form is to be completed in conjunction with CCR 7.0 / CCR 7.1 and forwarded by Email and filed as hard copy on board in CCR 7.2 folder



Date : 10/08/2018
Page : 3 of 3
Made by : QHSE
Approved by : MD

: 0

Rev. No.

