

CCR. 7.2 (A) - TANK CONDITION REPORT - CARGO TANKS

Date : 10/08/2018
Page : 1 of 3

Made by : QHSE

Approved by : MD Rev. No : 0

Vessel:	ANTIC				Location:	H COT COS CO, 5417 7A			
Cargo Tank:	<u> </u>				Insp Date :	11/10/2018			
Last Insp Date:		_							
(Frequency – Cargo Tanks – 6	Month	ly)							
General Condition:									
insulation : No	Yes	V ·	Type of i	insulatio	on: Rodawool				
Coating: No	Yes		Type of (Coating:					
Date Last Coating Mainten	ance:		Full Re-coat Part Re-Coat Touch-up NA						
Heating Colls: No Y	es 🗹	Туре:		mal o	ril				
Last Pressure Test Dates	Н	eating (Coils: 2	.8 10/ ₂	2018				
Tank Fitting & Equipment	Poor	Fair	Good	NA	Details Of	Required / Attention			
Hatch Coamings / Man hole covers			D			7 %			
Ladders / Steps / Handrails									
Cargo Drop Lines (Internal)		· 🔲 .		Ø					
Level Gauge (Internal)			· 🗆						
High Level Alarm (Internal)									
Temperature Sensor (Internal)			U						
UTI Sounding Pipe – Check it extends to full depth of tank, is earthed to bottom plating and that all holes are clear of obstruction			o d		UTI PTpa en	tends IIII man deels only .			
Tank Washing Machines						7 7 7 1			
Internal Frames									
Valve Reach Rod (If Any)									
Cargo Piping & Valves					V/W worth	Pipe dunnel.			
Stripping Lines & Valves									
Line Supports & Piping Dressers				Œ/					



CCR. 7.2 (A) - TANK CONDITION REPORT - CARGO TANKS

Date : 10/08/2018
Page : 2 of 3

Made by : QHSE
Approved by : MD
Rev. No : 0

[=]				· ·				
		<u>u</u>						
		D)						
			回	·				
		D)						
			U					
			W.					
		K						
			13					
Condition Of Tank Structure <u>Describe Details Of Any Fractures, Substantial Corrosion, Localised Pitting, Buckling,</u> <u>Condition Of Coating (Good, Fair, Poor), Hard Rust, Areas of Penetrations, Leakage from Adjacent Compartments</u>								
Good = Minor Spot Rust Only Fair = Local Breakdown Only Poor = General Breakdown or Hard Rust Condition of fourth fund Sales feety.								
	O O O O O O O O O O O O O O O O O O O	Condition Fractures, Sor), Hard Rus	Condition Of Tany Fractures, Substantor), Hard Rust, Areas	Condition Of Tank Stray Fractures, Substantial Conor), Hard Rust, Areas of Pen				

Chief Officer

X


To be completed in conjunction with CCR 7.0 & forwarded by Email & filed on board in CCR 7.2 Folder



CCR. 7.2 (A) - TANK CONDITION REPORT - CARGO. TANKS

Date : 10/08/2018
Page : 3 of 3

Made by : QHSE
Approved by : MD
Rev. No : 0





CCR. 7.2 (A) - TANK CONDITION REPORT -- CARGO TANKS

Date : 10/08/2018
Page : 1 of 3
Made by : QHSE
Approved by : MD
Rev. No : 0

	Vessel: _ Cargo Tank: _	BITO AT		<u>4</u>			Location:	losco shipyond	
ļ	Last Insp Date:		_	_					
	(Frequency – C	argo Tanks – (6 Month	y)					
	<u>General Condi</u>	tion:							
	Insulation :	No	Yes		Type of I	insulati	on: Rock wo	oo)	
	Coating:	No	Yes		Type of (Coating	:		•
	Date Last Co	pating Mainter	nance:		Full NA	Re-coa	at ☐ Part Re-C	Coat 🗌 Touch-up 🗍	
	Heating Col	ls: No 🗌 🐧	res 📝	Туре:	-16°	ታ ተ	انده ا		•
	Last Pressur	e Test Dates	H	eating (Coils:	&8/10	12018		
Tan	k Fitting & Equ	dpment	Poor	Fair	Good	NA	Details C	Of Required / Attention	
			1 1						•

Date Last Coating Mainten	ance:		Full NA	Re-coa	t 🗌 Part Re-Coat 🗍 Touch-up 🛄
Heating Colls: No Y	es 🔽	Type:	"The		انه ا
Last Pressure Test Dates	H	leating	Coils:	&5/10	72018
Tank Fitting & Equipment	Poor	Fair	Good	NA	Details Of Required / Attention
Hatch Coamings / Man hole covers			Ø		
Ladders / Steps / Handralls			Ø		
Cargo Drop Lines (Internal)				Ø	
Level Gauge (tnternal)					
High Level Alarm (Internal)			Ø		
Temperature Sensor (Internal)			Ø		
UTI Sounding Pipe Check it extends to full depth of tank, is earthed to bottom plating and that all holes are clear of obstruction			Ø		UTI pipe extends till mown deek only
Tank Washing Machines				Ø	
Internal Frames				Ø	
Valve Reach Rod (If Any)				凶	·
Cargo Piping & Valves				Q	viv inside pipe tunnel
Stripping Lines & Valves				Ø	
Line Supports & Piping Dressers				d	



CCR. 7.2 (A) - TANK CONDITION REPORT -- CARGO TANKS

Date : 10/08/2018
Page : 2 of 3

Made by : QHSE
Approved by : MD
Rev. No : 0

lytaster,

Suction Well			Q				
Bellmouth			Ø				
Heating Colls			Ø				
Foundation & Support Of Heating Coils			N		*** · · · · · · · · · · · · · · · · · ·		
Hydraulic Lines & Valves				Ø			
Rust / Scale Formation			Ø				
Coating				Ø	į		
Tank Bottom Insulation			Ø				
Port Bulkhead insulation				Ø			
Starboard Bulkhead Insulation			Ø				
Centre Line Bulkhead (Insulation / Coating)				Ø			
Forward Bulkhead (Insulation / Coating)			Ø				
AFT Bulkhead (Insulation / Coating)				Ø			
Under-Deck / Deck Head			Ø		·		
Stringers And Girders				Q			
Condition Of Tank Structure Describe Details Of Any Fractures, Substantial Corrosion, Localised Pitting, Buckling.							
Condition Of Coating (Good, Fair, Poor), Hard Rust, Areas of Penetrations, Leakage from Adjacent Compartments							
Good = Minor Spot Rust Only							
Fair = Local Breakdown Only							
Poor = General Breakdown or Hard Rust							
General condition of Got found setisfety.							

Chief Officer

To be completed in conjunction with CCR 7.0 & forwarded by Email & filed on board in CCR 7.2 Folder



CCR. 7.2 (A) - TANK CONDITION REPORT - CARGO TANKS

Date : 10/08/2018
Page : 3 of 3
Made by : QHSE
Approved by : MD
Rev. No : 0

