

Date : 10/08/2018
Page : 1 of 3
Made by : QHSE
Approved by : MD
Rev. No : 0

Vessel: _ BITU ATLAN	¶¢.		Location: Losco Shipyand Insp Date: 04/09/2018					
Cargo Tank: 3 P MI	31		Insp Date: 0'1/09/2-18					
(Frequency : Ballast Tanks Bi-	Annuall	y, Fresi	h Water	Tanks A	knnually)			
General Condition: 54	· stil	J ,		•				
Coating: No	Yes	Ø	Type of	Coating	e epony			
Date Last Coating Maint	enance	<b>:</b>	Full Re	-coat [	Part Re-Coat ☐ Touch-up ☑ 02/09/2018			
Tank Fitting & Equipment	Poor	Falr	Good	NA	Details Of Required / Attention			
Hatch Coamings / Man hote covers								
Ladders / Steps / Handralla								
Level Gauge (Internal)								
Sounding Pipes & Striking Plate								
Internal Frames			Ø					
Valve Reach Rod				Ø				
Eductor Lines & Valves				Ø	I/v inside lipe thunnel			
Line Supports & Piping Dressers				Ø	•			
Suction Well				Ø				
Bellmouth			Ø					
Hydraulic Lines & Valves				ব				
Fixed Gas Detections Lines & Filters			Image: second control of the control of					
Ballast Line & Valves				Ø	vlv inside pipe framel			
Anodes (If Fitted)								
Rust / Scale Formation					··			
Tank Bottom Coating			Ø					
Port Bulkhead Coating			Ø					
Starboard Bulkhead Coating								



Date: : 10/08/2018 Page : 2 of 3 Made by : QHSE

Approved by : MD Rev No.

	 			1107:140
Forward Bulkhead Coating		Ø		
Aft Bulkhead Coating		Ø		
Under-Deck / Tank Top		Ą		
Stringers And Girders		Ø		
Tank Vents		Ø		
Mud		Ø		
Gauge Glass –FW tanks			Ø	

Condition	Οt	Tank	Structur	e

Describe Details Of Any Fractures, Substantial Corrosion, Localised Pitting, Buckling, Condition Of Coating (Good, Fair, Poor), Hard Rust, Areas of Penetrations, Leakage from Adjacent Compartments

Good = Minor Spot Rust Only

Fair = Local Breakdown Only

Poor = General Breakdown or Hard Rust

General Remarks / Action Required:

WET was spot chipped / landow dury day of cla. Preser


Chief Officer

This form is to be completed in conjunction with CCR 7.0 / CCR 7.1 and forwarded by Email and filed as hard copy on board in CCR 7.2 folder



Date : 10/08/2018
Page : 3 of 3

Made by : QHSE
Approved by : MD
Rev. No : 0





Starboard Bulkhead Coating

Vessel: \_ BITU ATLANTIC

### CCR. 7.2 (B) - TANK CONDITION REPORT - BALLAST / FRESH WATER TANKS

Location:

Date : 10/08/2018
Page : 1 of 3
Made by : QHSE

Approved by : MD Rev. No : 0

Cosco Shipmand

Carg	go Tank: <u>'3\$ 炒ら'</u>	<u>T</u>	-			Insp Date: 13/09/2018					
(Fre	(Frequency : Ballast Tanks Bi-Annually, Fresh Water Tanks Annually)										
Gen	General Condition: Salis Journ										
	Coating: No	Yes		Type of	Coating	: EDOXY					
	Date Last Coating Maint	enance	:	Full Re-	-coat 🗆	Part Re-Coat Touch-up 10/09/18					
Tank Fi	tting & Equipment	Poor	Fair	Good	NA	Details Of Required / Attention					
Hatch Coami	ngs / Man hole covers			Ø							
Ladders / Sta	eps / Handrails			<b>2</b> ′							
Level Gauge	(Internal)			Ø							
Sounding Pip	oes & Striking Plate			Ø							
Internal Fram	nes			Ø							
Valve Reach	Rod .				Ø						
Eductor Line	s & Valves				Ø	V/v whide pipe tunnel					
Line Support	s & Piping Dressers				☑^						
Suction Well					Ø						
Bellmouth				Ø							
Hydraulic Lin	es & Valves										
Fixed Gas De	stections Lines & Filters										
Ballast Line &	& Valves					y/v inside apetunnes					
Anodes (If Fi	tted)			<u>P</u>							
Rust / Scale	Formation			Ø							
Tank Bottom	Coating	· 🔲		₫							
Port Bulkhea	d Coating			Ø							



Date : 10/08/2018
Page : 2 of 3

Made by : QHSE

Approved by : MD

Rev. No. 10

i				1104: 145
Forward Bulkhead Coating				
Aft Bulkhead Coating		Ø		:
Under-Deck / Tank Top		Ø		
Stringers And Girders		Ø		
Tank Vents		Image: Control of the		
Mud		Ø		
Gauge Glass –FW tanks			Ø	

Condition	Of	Tank	Str	uctur	¢
-----------	----	------	-----	-------	---

Describe Details Of Any Fractures, Substantial Corrosion, Localised Pitting, Buckling, Condition Of Coating (Good, Fair, Poor), Hard Rust, Areas of Penetrations, Leakage from Adjacent Compartments

Good = Minor Spot Rust Only

Fair = Local Breakdown Only

Poor = General Breakdown or Hard Rust

General Remarks / Action Required: -

WBT was spot chapped / Painter during daydocks. Peresent tank condition very good,

Chief Officer


Master

This form is to be completed in conjunction with CCR 7.0 / CCR 7.1 and forwarded by Email and filed as hard copy on board in CCR 7.2 folder



Date : 10/08/2018
Page : 3 of 3

Made by : QHSE
Approved by : MD
Rev. No : 0





#### CCR. 7.2 (B) - TANK CONDITION REPORT - BALLAST FRESH WATER TANKS

Date : 10/08/2018 Page : 1 of 3 Made by QHSE Approved by : MD Rev. No . 0

Vessel: _ Britu Atlier	ĀUÇ		Location: Posco Ship yourd Insp Date: 04/09/2016						
Cargo Tank:				Insp Date: 04/09/2016					
(Frequency : Ballast Tanks Bi-	Annual	y, Fresi	h Water	Tanks A	Annually)				
General Condition: _Self Shelf									
Coating: No	Yes	V	Type of	_	•				
Date Last Coating Maint	enance	<del>, ,, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,</del>	Full Re	-coat	Part Re-Coat Touch-up 2 02/27/15				
Tank Fitting & Equipment	Poor	Falr	Good	NA	Details Of Required / Attention				
Hatch Ceamings / Man hole covers			Ø						
Ladders / Steps / Handrails			Ø						
Level Gauge (Internal)			<b>\(\overline{\pi}\)</b>						
Sounding Pipes & Striking Plate			\alpha'						
Internal Frames			Ø						
Valve Reach Rod				Ø					
Eductor Lines & Valves				Ø	VIV inside pipe townel				
Line Supports & Piping Dressers				Ø					
Suction Well				Ø					
Bellmouth .			Ø						
Hydraulic Lines & Valves				Ø					
Fixed Gas Detections Lines & Filters									
Ballast Line & Valves				Ø	VIV inside pre tunnel				
Anodes (If Fitted)					·				
Rust / Scale Formation					· · · · · ·				
Tank Bottom Coating									
Port Bulkhead Coating									
Starboard Bulkhead Coating									



Date : 10/08/2018
Page : 2 of 3
Made by : QHSE

Approved by : MD Rev. No : 0

	 		1107.140	
Forward Bulkhead Coating		Ø		
Aft Bulkhead Coating		Ø		
Under-Deck / Тапк Тор		Ø		
Stringers And Girders		Ø		
Tank Vents		Ø,		
Mud		d		
Gauge Glass FW tanks				***

Conditio	Condition Of Tank Structure  Describe Details Of Any Fractures, Substantial Corrosion, Localised Pitting, Buckling,  Condition Of Coating (Good, Fair, Poor), Hard Rust, Areas of Penetrations, Leakage from Adjacent Compartments							
Fair ≈ Loca	inor Spot Rust Only al Breakdown Only peral Breakdown or Hard Rust							
General R	emarks / Action Required:							
WB Por	esent condition of conting very good							

Chief Officer


Master

This form is to be completed in conjunction with CCR 7.0 / CCR 7.1 and forwarded by Email and filed as hard copy on board in CCR 7.2 folder



Date : 10/08/2018 Page : 3 of 3 Made by : QHSE

Approved by : MD Rev. No : 0





Date : 10/08/2018
Page : 1 of 3

Made by : QHSE
Approved by ; MD
Rev. No : 0

Ves	sel: _ BIN ATLA	MITTE			Lo	cation: Cose Suppard			
Carş	go Tank: <u>45</u>	NBT			Insp Date: 04/09/2018				
(Fre	quency : Ballast Tanks Bi-	-Annual	ly, Fres	h Water	Tanks .	Annually)			
Gen	eral Condition: Sal	18/00	d or						
		Yeş		Type of	Coatin	e: Elom			
	Date Last Coating Main	tenance	;	Full Re	-coat [	☐ Part Re-Coat ☐ Touch-up ☐ 0 1/0 1/2016			
Tank Fi	tting & Equipment	Poor	Fair	Good	NA	Details Of Required / Attention			
Hatch Coami	ngs / Man hole covers			乜					
Ladders / Ste	eps / Handrails			Ø					
Level Gauge	(Internal)			Ø					
Sounding Pip	es & Striking Plate								
Internal Fram	nas								
Valve Reach	Rod				Ø	-			
Eductor Lines	s & Valves				Ø'				
Line Supports	s & Piping Dressers				Ø				
Suction Well					Ø				
Belimouth				Q'					
Hydrautic Lin	es & Valves				Ø				
Fixed Gas De	stections Lines & Filters			Ø					
Ballast Line &	k Valves				Ø	V/v inside lipe tunnel			
Anodes (If Fit	tted)			Z/					
Rust / Scale i	Formation			Ø					
Tank Bottom	Coating			g					
Port Bulkhea	d Coating			Ø					
Starboard Bu	Ikhead Coating			Ø					



Date : 10/08/2018 Page : 2 of 3

	<u> </u>
Made by	: QHSE
Approved	by: MD
Made by Approved Rev. No	: 0

	 ,			1101.110
Forward Bulkhead Coating				
Aft Bulkhead Coating		Ø		
Under-Deck / Tank Top		Ø		
Stringers And Girders		₫		
Tank Vents		Ø		
Mud		Ø		
Gauge Glass FW tanks			Ø	

Condition	Of Tank	Structure

Describe Details Of Any Fractures, Substantial Corrosion, Localised Pitting, Buckling, Condition Of Coating (Good, Fair, Poor), Hard Rust, Areas of Penetrations, Leakage from Adjacent Compartments

Good = Minor Spot Rust Only

Fair = Local Breakdown Only

Poor = General Breakdown or Hard Rust

General Remarks / Action Regulred:

WEV Was sport the plant / Painter duny 5/4 period. Present dank.

Chief Officer

Master

This form to be completed in conjunction with CCR 7.0 / CCR 7.1 and forwarded by Email and filed as hard copy on board in CCR 7.2 folder



Date : 10/08/2018
Page : 3 of 3

Made by : QHSE

Approved by : MD Rev. No : 0

