



## Maritec Tanker Management

### Incident Reports Details

Ship File No : N/A  
Office File No : N/A  
Form No : N/A  
Issue : N/A  
Revision : N/A  
Rev Date : N/A

Vessel : Asphalt Teranga	Defect ID : 153	NCR # : 20/2023	Is NCR ? : Yes
--------------------------	-----------------	-----------------	----------------

#### Defect Details

AT AGIOS THEODOROI, ON 4TH AUGUST PSC INSPECTOR FOUND THATSMOKE DETECTORS AT PAINT STORE AND PURIFIER ROOM WERE INOPERATIVE.

Requisition Code :

#### Categories

Primary :	Incident	Inspector - Internal :		Vessel Dept :	Deck
Secondary :	Procedures not Followed	Inspector External :		Office Dept :	Safety
		Inspection Date :			

#### Applicable Dates

Date Raised : 04-Aug-2023	ETC : 06-Aug-2023	Date Completed : 05-Aug-2023
---------------------------	-------------------	------------------------------

#### Other Details

Priority : Normal	Assigned By : Vessel	Verified By :
Display in Daily Meeting? : No	SFI :	Verified On :

#### Causes

SMOKE DETECTORS NOT GIVING ALARM TO SMOKE.

#### Corrective Action

AT PAINT ROOM HUMIDITY

#### Preventive Action

CONTINUOUS MAINTENANCE AND REPLACEMENT OF MALFUNCTIONING UNITS

#### Applicable Tags

#### Follow Up

On	By	Follow Up	
05/Aug/2023	Asfaha Tekeste Gebremichael   Staff Code - 10368 - MST	AWAITING OFFICE ACTION for this job has been changed to Yes	

#### Before & After Pictures

Before	After
--------	-------

