



Maritec Tanker Management Private Limited

Incident Reports Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Asphalt Teranga	Defect ID : 153	NCR # : 20/2023	Is NCR ? : Yes
--------------------------	-----------------	-----------------	----------------

Defect Details

AT AGIOS THEODOROI, ON 4TH AUGUST PSC INSPECTOR FOUND THATSMOKE DETECTORS AT PAINT STORE AND PURIFIER ROOM WERE INOPERATIVE.

Requisition Code :

Categories

Primary :	Incident	Inspector - Internal :		Vessel Dept :	Deck
Secondary :	Procedures not Followed	Inspector External :		Office Dept :	Safety
		Inspection Date :			

Applicable Dates

Date Raised : 04-Aug-2023	ETC : 06-Aug-2023	Date Completed : 05-Aug-2023
---------------------------	-------------------	------------------------------

Other Details

Priority : Normal	Assigned By : Vessel	Verified By : Nawin Khaware
Display in Daily Meeting? : No	SFI :	Verified On : 03/Oct/2023

Causes

SMOKE DETECTORS NOT GIVING ALARM TO SMOKE.

Corrective Action

AT PAINT ROOM HUMIDITY

Preventive Action

CONTINUOUS MAINTENANCE AND REPLACEMENT OF MALFUNCTIONING UNITS

CONTRIBUTING FACTORS

Follow Up

On	By	Follow Up	
05/Aug/2023	Asfaha Tekeste Gebremichael Staff Code - 10368 - MST	AWAITING OFFICE ACTION for this job has been changed to Yes	

Before & After Pictures

Before	After
--------	-------

