

Maritec Tanker Management Private Limited

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Incident Reports Details

Vessel: Asphalt Teranga Defect ID: 154 NCR #: 21/2023 Is NCR ?: Yes

Defect Details

AT AGIOI THEODOROI ON 4TH AUGUST PSC INSPECTOR OBSERVED THE WBT VENTILATORS AND MUSHROOM TYPE VENTILATORS ON MAIN DECK FOUND WITH SPOT OF RUST.

Requisition Code:

Categories							
Primary :	Incident	Inspector - Internal:		Vessel Dept:	Deck		
Secondary :	Other	Inspector External :		Office Dept:	Technical		
		Inspection Date :					

Applicable Dates

Other Details

Priority: Normal

Assigned By: Vessel

Verified By: Nawin Khaware

Display in Daily Meeting?: No

SFI:

Verified On: 03/Oct/2023

Causes

RUST DO TO WEAR AND TEAR

Corrective Action

CHIPPING SCRAPPING CLEAN AND PAINT

Preventive Action

FOLLOW REGULAR MAINTENANCE SCHEDULE

CONTRIBUTING FACTORS

Follow Up


On	Ву	Follow Up	
28/Aug/2023	Alexander DUBAKOV Staff Code - 10564 - C/OFF	AWAITING OFFICE ACTION for this job has been changed to Yes	
09/Aug/2023	Asfaha Tekeste Gebremichael >br/> Staff Code - 10368 - MST	Spot chipping done, wire brushed, prepared the area, and finally applied paint.	

Before & After Pictures


Incident Reports Details Printed On: 20-Mar-2024 1/4

Before After





















Notification



File Not Uploaded

Notification



File Not Uploaded

Notification



File Not Uploaded

Notification



File Not Uploaded



Notification



File Not Uploaded