



Maritec Tanker Management Private Limited

Incident Reports Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Bitu River	Defect ID : 56	NCR # : 9/2023	Is NCR ? : Yes
---------------------	----------------	----------------	----------------

Defect Details

During cargo discharge completion at Cape Town,awaiting the shore to start cargo hoses air blow,sudden pressure observed at ship's manifold.Noticed that shore staff already commenced to blow shore line without informing the ship and shore valve towards ship's cargo hose was in open position which caused the sudden increase in pressure and causing the damage of ship's cargo hose no.2

Requisition Code :

Categories

Primary :	Incident	Inspector - Internal :		Vessel Dept :	Deck
Secondary :	Safe Working Procedures not Followed	Inspector External :		Office Dept :	Operations
		Inspection Date :			

Applicable Dates

Date Raised : 10-Sep-2023	ETC : 30-Sep-2023	Date Completed : 28-Sep-2023
---------------------------	-------------------	------------------------------

Other Details

Priority : Normal	Assigned By : Vessel	Verified By : Nawin Khaware
Display in Daily Meeting? : No	SFI :	Verified On : 06/Oct/2023

Causes

Terminal tried to blow their shore line before ship's blowing the cargo hoses without informing ship's staff and without closing the shore valve .

Corrective Action

Call terminal to stop air blowing

Preventive Action

To be stated in ship-shore cargo operation agreement the air blowing procedure. Going forward, only vessel will be doing airblowing upon completion of cargo operation or as requested by the terminal to ensure pressure is regulated properly so that damage to hoses could be avoided.

CONTRIBUTING FACTORS

Descriptions

Cargo Damage

Root Causes- Personal Factor

Inadequate Communication

Direct Causes- Unsafe Conditions

Others
Direct Causes- Unsafe Acts
Failure to Warn
Job Factors
Incorrect or Insufficient or Unclear Instructions Given
Personal Factors
Lack of Knowledge
Substandard Acts
Failure to follow procedure
Substandard Conditions
Defective Materials

Follow Up

On	By	Follow Up	
14/Sep/2023	Marin Ceapa Staff Code - 10446 - MST	Factory and on board test certificates of cargo hose	Link1 Link2
14/Sep/2023	Marin Ceapa Staff Code - 10446 - MST	CCR log	Link1
14/Sep/2023	Marin Ceapa Staff Code - 10446 - MST	SSCL	Link1
14/Sep/2023	Marin Ceapa Staff Code - 10446 - MST	Discharge port and Cargo info agreement	Link1
13/Sep/2023	Marin Ceapa Staff Code - 10446 - MST	LOP raised to terminal	Link1

Before & After Pictures


Before	After
---------------	--------------



Notification




File Not Uploaded



Notification



File Not Uploaded



Notification



File Not Uploaded