



Maritec Tanker Management

Incident Report's Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Bitu Express	Defect ID : 123	NCR # : 9/2021	Is NCR ? : Yes
-----------------------	-----------------	----------------	----------------

Defect Details

Deck Bunker line on portside, front of accommodation, has leakage from a hole on pipe.

Requisition Code :

Categories

Primary :	Incident	Inspector - Internal :		Vessel Dept :	Deck
Secondary :	Other	Inspector External :		Office Dept :	Operations
		Inspection Date :	13-Sep-2021		

Applicable Dates

Date Raised : 13-Sep-2021	ETC : 18-Sep-2021	Date Completed : 29-Sep-2021
---------------------------	-------------------	------------------------------

Other Details

Priority : Normal	Assigned By : Vessel	Verified By : Nawin Khaware
Display in Daily Meeting? : No	SFI :	Verified On : 01/Nov/2021

Causes

Poor condition of material on that part of bunker pipe

Corrective Action

Currently temporarily repaired

Preventive Action

To be renewed that part of pipe

Applicable Tags

Descriptions

Pollution

Root Causes- Management Factors

Inadequate Monitoring / Supervision

Direct Causes- Unsafe Acts

Failure to Follow Repair / Maintenance Instructions

Job Factors

Inadequate Planning

Follow Up			
On	By	Follow Up	
28/Oct/2021	Nawin Khaware	Hope pipe has been renewed. Update the details and photographs of permanent repair.	
15/Sep/2021	Gelu Antin Staff Code - 10124 - MST	Currently temporarily repaired.	Link1 Link2

Before & After Pictures

Before	After
--------	-------



