

Maritec Tanker Management Incident Report's Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Defect Details

Port thruster high temperature safety activated and stopped the thruster. ship was transiting from trinidad to guyana. abnormal noise and vibration were observed in gearbox

Requisition Code:

Categories							
Primary :	Incident	Inspector - Internal:	Francis Timothy Monteiro	Vessel Dept:	Engine		
Secondary :	Other	Inspector External :		Office Dept:	Technical		
		Inspection Date :	01-Aug-2021				

Applicable Dates

Other Details

Priority: Urgent

Assigned By: Vessel

Verified By: Nawin Khaware

Display in Daily Meeting? : No SFI: Verified On : 28/Oct/2021

Causes

Material Failure

Corrective Action

Replaced new lower gearbox and changed oil with environmental friendly oil

Preventive Action

Maintain constant checks during rounds.

Applicable Tags

Follow Up

On	Ву	Follow Up	
28/Oct/2021	Nawin Khaware	Vessel called for DD at Santo Domingo for carrying out permanent repair of Port thruster. System is up for running and back to normal now. We can consider this report as closed now.	

Before & After Pictures

Before After

Incident Report's Details Printed On: 27-Jan-2022 1/2







