



Maritec Tanker Management Private Limited

Incident Reports Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Demerara	Defect ID : 83	NCR # :	Is NCR ? : No
-------------------	----------------	---------	---------------

Defect Details

ON 20.08.2023 DURING HOSE CONNECTION CREW FOUND HAMMERING PRESSURIZED HOSE WITH METAL HAMMER. IMMEDIATELY STOP WORK BY DUTY OFFICER AND EXPLAIN CONSEQUENCES AND NOT TO USED METAL HAMMER.

Requisition Code :

Categories

Primary :	Incident	Inspector - Internal :		Vessel Dept :	Deck
Secondary :	Safe Working Procedures not Followed	Inspector External :		Office Dept :	Operations
		Inspection Date :			

Applicable Dates

Date Raised : 20-Aug-2023	ETC : 01-Sep-2023	Date Completed : 01-Sep-2023
---------------------------	-------------------	------------------------------

Other Details

Priority : Normal	Assigned By : Vessel	Verified By : Nawin Khaware
Display in Daily Meeting? : No	SFI :	Verified On : 06/Oct/2023

Causes

Lack of knowledge.

Corrective Action

Concerned crew member was stopped from doing such an unsafe act and he was asked to stop the hammering work on pressurised hoses.

Preventive Action

All crew members were warned of carrying out such activity and they all were advised to follow the COSWP.

CONTRIBUTING FACTORS

Root Causes- Management Factors

Inadequate Monitoring / Supervision

Root Causes- Personal Factor

Lack of Knowledge

Direct Causes- Unsafe Acts

Other Substandard Act(s)

Substandard Acts

Failure to observe basic safety rules

Follow Up

On	By	Follow Up	
06/Oct/2023	Nawin Khaware	In future, please report such issues under unsafe act as it doesn't qualify for incident reporting.	

Before & After Pictures

Before	After
--------	-------