

# Maritec Tanker Management Incident Reports Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

#### **Defect Details**

During preparation for vetting inspection we made familiarization and training for crew.

This happen that MOB buoy Light and Smoke signal(Port side) was occasionally released and activated during demonstration of procedure.

Requisition Code:

Categories							
Primary :	Incident	Inspector - Internal:		Vessel Dept:	Deck		
Secondary :	Lack of Training	Inspector External :		Office Dept:	Safety		
		Inspection Date :					

## **Applicable Dates**

Other Details						
Priority : Normal	Assigned By: Vessel	Verified By :				
Display in Daily Meeting? : No	SFI:	Verified On:				

## Causes

Human factor - wrong action.

#### **Corrective Action**

Vessel raised urgent requisition BBLU-SF-V230085 - MOB buoy Light and Smoke signal and send to Purchase department. Temporarily instruction posted to use Starboard side MOB Smoke&Light signal buoy.

# **Preventive Action**

Extra training for all crew to use ship's Pyrotechnics.

# Applicable Tags

#### **Root Causes- Personal Factor**

Lack of Knowledge

## **Direct Causes- Unsafe Acts**

Improper Lifting, Handling or Storage

## **Job Factors**

Inadequate Familiarization

Incident Reports Details Printed On: 25-Jul-2023 1/3

Follow Up					
On	Ву	Follow Up			
01/Jul/2023	Vitaliy Klimenko   Staff Code - 10633 - MST	on 29/06/2023 already instoled in position new MOB.	Link1		
19/Jun/2023	Nawin Khaware	Items are on order and vessel expected to receive by 3rd week of June.			
02/Jun/2023	Valentin MITENKOV Staff Code - 10552 - MST	EXPECTED COMPLETION DATE for this job has been changed from 31/May/2023 to 24/Jun/2023			
24/May/2023	Valentin MITENKOV Staff Code - 10552 - MST	Vessel raised urgent requisition BBLU-SF-V230085 - MOB buoy Light and Smoke signal and send to Purchase department.			

# **Before & After Pictures**

# Before



# After





