



Maritec Tanker Management

Incident Reports Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Bahama Blue	Defect ID : 183	NCR # : 5/2023	Is NCR ? : Yes
----------------------	-----------------	----------------	----------------

Defect Details

During preparation for vetting inspection we made familiarization and training for crew. This happen that MOB buoy Light and Smoke signal(Port side) was occasionally released and activated during demonstration of procedure.

Requisition Code :

Categories

Primary :	Incident	Inspector - Internal :		Vessel Dept :	Deck
Secondary :	Lack of Training	Inspector External :		Office Dept :	Safety
		Inspection Date :			

Applicable Dates

Date Raised : 24-May-2023	ETC : 24-Jun-2023	Date Completed : 29-Jun-2023
---------------------------	-------------------	------------------------------

Other Details

Priority : Normal	Assigned By : Vessel	Verified By : Nawin Khaware
Display in Daily Meeting? : No	SFI :	Verified On : 04/Aug/2023

Causes

Human factor - wrong action.

Corrective Action

Vessel raised urgent requisition BBLU-SF-V230085 - MOB buoy Light and Smoke signal and send to Purchase department. Temporarily instruction posted to use Starboard side MOB Smoke&Light signal buoy.

Preventive Action

Extra training for all crew to use ship's Pyrotechnics.

Applicable Tags

Root Causes- Personal Factor

Lack of Knowledge

Direct Causes- Unsafe Acts

Improper Lifting, Handling or Storage

Job Factors

Inadequate Familiarization

Follow Up			
On	By	Follow Up	
01/Jul/2023	Vitaliy Klimentko Staff Code - 10633 - MST	on 29/06/2023 already instoled in position new MOB.	Link1
19/Jun/2023	Nawin Khaware	Items are on order and vessel expected to receive by 3rd week of June.	
02/Jun/2023	Valentin MITENKOV Staff Code - 10552 - MST	EXPECTED COMPLETION DATE for this job has been changed from 31/May/2023 to 24/Jun/2023	
24/May/2023	Valentin MITENKOV Staff Code - 10552 - MST	Vessel raised urgent requisition BBLU-SF-V230085 - MOB buoy Light and Smoke signal and send to Purchase department.	

Before & After Pictures

Before	After
--------	-------



