

Maritec Tanker Management Private Limited

Ship File No : N/A Office File No : N/A Form No : N/A Issue : N/A Revision : N/A

Rev Date

Incident Reports Details

Vessel: Asphalt Teranga Defect ID: 201 NCR #: 42/2023 Is NCR ?: Yes

Defect Details

Last night during navigation in our route, Gyro Heading was found with 20-30 degr error. Autopilot shift in Magnetic Compass mode.

Requisition Code:

Categories				
Primary :	Incident	Inspector - Internal:	Vessel Dept:	Deck
Secondary :	Other	Inspector External :	Office Dept:	Technical
		Inspection Date :		

Applicable Dates

Other Details

Priority: Urgent Assigned By: Vessel Verified By:

Display in Daily Meeting? : No SFI: Verified On :

Causes

Malfuction Gyrocompass

Corrective Action

Temporary change auto pilot to Magnetic Compass

Preventive Action

Made RA, infored office, follow instructions

CONTRIBUTING FACTORS

Follow Up

On	Ву	Follow Up	
08/Dec/2023	Temilade Joshua Obogbeni Staff Code - 10587 - 2/OFF	Gyro compass technician arranged for service the gyro compass in dry dock	

Before & After Pictures

Before	After
Delore	Arter

Incident Reports Details Printed On: 14-Dec-2023 1/2



B. 15.0 - FAMILIARIZATION LIST

Date	:	01/01/2023
Page	:	1 of 1
Made by	:	QHSE
Approved by	:	GM
Rev. No		01

Vessel : MT ASPHALT TERANGA

All Duty Officers have Acknowledge that they have Undertaken training of changing the auto pilot feed from gyro compass to magnetic compass.

Training: FAMILIARIAZATION TO CHANGE THE AUTO PILOT FEED FROM GYRO COMPASS TO MAGNETIC COMPASS

1.IVANOV VITALY CHIEF OFFICER

2. PRAKASH KUMAR 2ND OFFICER Shaller

3. GATHIE KHADIM JUNIOR OFFICER GARLE

The above training and demonstrated was carried out onboard under the supervision of the master.



Notification



File Not Uploaded

Printed On: 14-Dec-2023 2/2 Incident Reports Details

To be used as evidence of familiarization of various manuals, standing orders & filed as hard copy along with the Manual / Instructions