l
-
MARTEC TANKER MANAGEMENT

Maritec Tanker Management Private Limited

Incident Reports Details

Vessel :	Asphalt Teranga	Defect II): 188	NCR # :	30/2023	ls N	ICR ? : Yes			
Defect Details										
During PSC inspection on 29.09.2023										
In the coastal waters, there is no evidence that the ship's position was checked by an independent means of position fixing. (No LOPs were found in ECDIS). Master instructed to check the ship position as per requirements from now on.										
Requisition Code :										
Categories										
Primary :	Incident	Inspe	Inspector - Internal :		Ve	essel Dept:	Deck			
Secondary	/: Lack of Training	Inspe	ctor External :	C		ffice Dept :	Safety			
		Inspe	ction Date :							
Applicable Dates										
Date Raised : 29-Sep-2023			ETC : 02-Oct-2023			Date Completed : 01-Oct-2023				
Other Details										
Priority :	Normal		Assigned By:	Vessel	١	Verified By : Nawin Khaware				
Display in Daily Meeting? : No			SFI :		١	Verified On : 13/Oct/2023				
Causes										
Lack of trair	ning									
Corrective Action										
Training carried out on position fixing (LOP) on ECDIS										
Preventiv	e Action									
Company policies and procedures must be adhered to always and passage plan instructions to be followed as per position fixing means and methods										
Applicable Tags										
Root Causes- Job Factor										
Inadequate Leadership and / or Supervision										
Root Causes- Management Factors										
Inadequate Monitoring / Supervision										
Root Causes- Personal Factor										
Lack of Knowledge										

Job Factors								
Inadequate Planning								
Substandard Acts								
Failure to follow procedure								
Follow Up								
On	Ву	Follow Up						
13/Oct/2023	Nawin Khaware	Consider this point as closed now basis submitted evidence.						
Before & After Pictures								
Before			After					
SHIP NAME: ASPHALT TERAN	IGA IK ENTRIES & POSITION FIXING (LOP)		Notification					
TRAINING REPORT:			File Not Uploaded					

Master carried out training for deck officer on how to write log entries correctly and position fixing (LOP) on ECDIS. Company policies and procedures must be adhered to always and passage plan instructions to be followed as per position fixing means and methods.

Well understood.

ch/off 2/Off Jr/Off

Master