



Maritec Tanker Management Private Limited

Incident Reports Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Asphalt Teranga	Defect ID : 198	NCR # : 40/2023	Is NCR ? : Yes
--------------------------	-----------------	-----------------	----------------

Defect Details

During PSC inspection on 29.09.2023

The vessel was grounded during the maneuver to enter the Mangalia Port. The Class Survey Report has to be provided to the Romanian PSC Department before the ship's departure from Mangalia Port.

Requisition Code :

Categories

Primary :	Incident	Inspector - Internal :		Vessel Dept :	Deck
Secondary :	Procedures not Followed	Inspector External :		Office Dept :	Safety
		Inspection Date :			

Applicable Dates

Date Raised : 29-Sep-2023	ETC : 30-Sep-2023	Date Completed : 30-Sep-2023
---------------------------	-------------------	------------------------------

Other Details

Priority : Normal	Assigned By : Vessel	Verified By : Nawin Khaware
Display in Daily Meeting? : No	SFI :	Verified On : 12/Oct/2023

Causes

Vessel bottom touching at the forward part

Corrective Action

Underwater survey carried out

Preventive Action

Comply with company policy on navigational safety

CONTRIBUTING FACTORS

Follow Up

On	By	Follow Up	
----	----	-----------	--

Before & After Pictures

Before	After
--------	-------




SEA STAR DIVING SERVICE SRL
 REG: RO181812Z J137292004
 IBAN EUR: RO20BRDE1405V20324801400
 IBAN RON: RO20BRDE1405V20324801400
 SWIFT: EROBU1 BRD Lapu-lapu, Constanta, Romania
 Address: 15 cai. Dobrii Eugeniu st. D.35, ap.40,
 900502, Constanta, Romania
 Phone: +40 743 144 316, +40 722 728 603
 Email: office@divingservices.eu



SEASTAR DIVING SERVICE SRL
 INCERTE Nr. 89
 ESIRE
 Ziua: 30 Luna: 09 Anul: 2023

**DIVER'S REPORT:
 IN-WATER SURVEY**

SHIP INFORMATION



NAME	ASPHALT TERANGA
IMO NUMBER	9263942
FLAG / HOMEPORT	PANAMA / PANAMA
LENGTH	108.5 M
BREADTH	19.80 M
DEPTH	10.6 M
TYPE	ASPHALT TANKER

RINA
 M. Măscaru
 RINA Service S.p.A.
 Witness and reviewed
 Mangalia, RO
 30/09/2023
 Total page: 5
 page 1 of 5

Notification

i File Not Uploaded



SEA STAR DIVING SERVICE SRL
 REG: RO181812Z J137292004
 IBAN EUR: RO20BRDE1405V20324801400
 IBAN RON: RO20BRDE1405V20324801400
 SWIFT: EROBU1 BRD Lapu-lapu, Constanta, Romania
 Address: 15 cai. Dobrii Eugeniu st. D.35, ap.40,
 900502, Constanta, Romania
 Phone: +40 743 144 316, +40 722 728 603
 Email: office@divingservices.eu



RINA
 Via Genova, 12 - 16128 Genova
 Tel. +39 010 53881
 Fax +39 010 538100

**CERTIFICATE OF APPROVAL
 OF SERVICE SUPPLIER**

CERTIFICATE NO. 2020XR140

This is to certify that

SC SEA STAR DIVING SERVICE SRL
 STR. CAI. DOBRII EUGENIU NR.15,35,36,40
 Constanta - Constanta ROMANIA

Has been approved in compliance with the
 RINA "RULES FOR THE CERTIFICATION OF SERVICE SUPPLIERS"
 for the supply of the following services to ships and other units classed by RINA:
C - In-water survey of ships and mobile offshore units

Issued in Constanta on 7/10/2020 This Certificate is valid from the date of the initial audit until 10/12/2023

This certificate consists of this sheet plus an attachment

RINA

 Marius Fugaru



Notification

i File Not Uploaded



SEA STAR DIVING SERVICE SRL
 REG. RO37678027 J137299/0004
 IBAN EUR: RO386800140312015048914403
 IBAN RON: RO448800140312015048914403
 SWIFT: EROR963 EROR
 Lăzarieni, Constanța, România
 Adresă: 15 cp. Dobrița Eugenia, nr. 21.X5, nr.40,
 801002, Constanța, România
 Phone: +40 743 144 316, +40 722 728 803
 Email: office@divingservices.eu



BOTTOM SURVEY

Antifouling state	Sea incrustations	Deformations	Corrosion	Fractures	Welding	Other
good condition	no	no	no	no	no visible damages	/

Comments: On the bottom, at the bow area, on port side, starting below the bowthruster, were observed two indentations of approx. 1 m length x 40 cm wide x 3 cm depth and 2 m length x 60 cm wide x 3 cm depth. Multiple scratches were found on the port side area of the bottom. No fractures or holes were observed.

SEACHESTS

	Gratings	Sea incrustations	Other
Port side	present, in good condition	clear	/
Starboard side	present, in good condition	clear	/

Comments: /

PROPELLER SURVEY

	Blade condition	Fissures	Fractures	Sea incrustations	Other
Blade A	good	no	no	no	/
Blade B	good	no	no	no	/
Blade C	good	no	no	no	/
Blade D	good	no	no	no	/

Comments: /

RUDDER SURVEY

Rudder blade	Fissures	Fractures	Sea incrustations	Other
good condition	no	no	no	/

Comments: No deformation, damages or cracks were observed. Rudder flap has been observed with a 20 cm misalignment, from position zero of the blade, in port side.

Notification

