

Maritec Tanker Management Incident Reports Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel: Bitu Atlantic Defect ID: 264 NCR #: 3/2023 Is NCR ?: Yes

Defect Details

Fitter Mr.Acchelal while removing spool piece from the Scrubber sea water line, the Spool piece fall on his left hand middle finger and injured with small cut.

Requisition Code:

Categories					
Primary :	Incident	Inspector - Internal:		Vessel Dept:	Engine
Secondary :	Other	Inspector External :		Office Dept:	Safety
		Inspection Date :			

Applicable Dates

Date Raised: 30-Jan-2023 ETC: 04-Feb-2023 Date Completed: 06-Feb-2023

Other Details

Priority : Normal Assigned By : Vessel Verified By : Nawin Khaware

Display in Daily Meeting? : No SFI: Verified On : 09/Mar/2023

Causes

Uncoordination of workers during the job

Corrective Action

Work was stopped immediately, first aid was given to the person involved.

Preventive Action

Retraining to be carried out, the job must supervise by engineers

Applicable Tags

Descriptions

Injury

Root Causes- Job Factor

Inadequate Work Standards

Root Causes- Management Factors

Inadequate Monitoring / Supervision

Direct Causes- Unsafe Conditions

Incident Reports Details Printed On: 14-Jun-2023 1/3

Inadequate or Defective PPE

Job Factors

Inadequate Supervision

Personal Factors

Lack of Skill

Substandard Acts

Failure to observe basic safety rules


On By Follow Up O6/Feb/2023 Gelu Antin
Staff Code - 10124 resumed his daily activity. O1/Feb/2023 Nawin Khaware Complete all the sections - Causes, Corrective and preventive measures. also, upload the photographs of injuries and preferably the location where this incident took place.

Before & After Pictures

Before

After





Incident Reports Details Printed On: 14-Jun-2023 2/3







