



Maritec Tanker Management

Incident Report's Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Bitu Atlantic	Defect ID : 264	NCR # : 3/2023	Is NCR ? : Yes
------------------------	-----------------	----------------	----------------

Defect Details

Fitter Mr.Acchelal while removing spool piece from the Scrubber sea water line, the Spool piece fall on his left hand middle finger and injured with small cut.

Requisition Code :

Categories

Primary :	Incident	Inspector - Internal :		Vessel Dept :	Engine
Secondary :	Other	Inspector External :		Office Dept :	Safety
		Inspection Date :			

Applicable Dates

Date Raised : 30-Jan-2023	ETC : 04-Feb-2023	Date Completed : 06-Feb-2023
---------------------------	-------------------	------------------------------

Other Details

Priority : Normal	Assigned By : Vessel	Verified By : Nawin Khaware
Display in Daily Meeting? : No	SFI :	Verified On : 09/Mar/2023

Causes

Uncoordination of workers during the job

Corrective Action

Work was stopped immediately, first aid was given to the person involved.

Preventive Action

Retraining to be carried out , the job must supervise by engineers

Applicable Tags

Descriptions

Injury

Root Causes- Job Factor

Inadequate Work Standards

Root Causes- Management Factors

Inadequate Monitoring / Supervision

Direct Causes- Unsafe Conditions

Inadequate or Defective PPE
Job Factors
Inadequate Supervision
Personal Factors
Lack of Skill
Substandard Acts
Failure to observe basic safety rules

Follow Up

On	By	Follow Up	
06/Feb/2023	Gelu Antin Staff Code - 10124 - MST	The fitter's wound has healed, his finger is ok, and he has resumed his daily activity.	Link1
01/Feb/2023	Nawin Khaware	Complete all the sections - Causes, Corrective and preventive measures. also, upload the photographs of injuries and preferably the location where this incident took place.	

Before & After Pictures

Before	After
--------	-------



