



Maritec Tanker Management

Incident Report's Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Biskra	Defect ID : 41	NCR # : 2/2021	Is NCR ? : Yes
-----------------	----------------	----------------	----------------

Defect Details

Between 27th June and 30th June, because of swell at change of tide mooring ropes were parting, so we had to stop cargo operation and disconnect Hose for safety, and we had to cast off thrice from BITU ATLANTIC.

Requisition Code :

Categories

Primary :	Incident	Inspector - Internal :		Vessel Dept :	Deck
Secondary :	Other	Inspector External :		Office Dept :	Operations
		Inspection Date :			

Applicable Dates

Date Raised : 30-Jun-2021	ETC : 30-Jun-2021	Date Completed : 05-Jul-2021
---------------------------	-------------------	------------------------------

Other Details

Priority : Normal	Assigned By : Vessel	Verified By : Nawin Khaware
Display in Daily Meeting? : No	SFI :	Verified On : 06/Jul/2021

Causes

Bad weather lead to such incident.

Corrective Action

Vessel decided to stop the cargo operation & immediately cast off from Mother vessel.

Preventive Action

Weather forecast to be monitored continuously and abort STS operation in case if there's any indication of approaching bad weather.

Applicable Tags

Descriptions

Allison

Others

Root Causes- Job Factor

Inadequate Leadership and / or Supervision

Others

Root Causes- Management Factors

Inadequate Monitoring / Supervision
Root Causes- Personal Factor
Complacency / Over Confidence
Improper Assessment
Direct Causes- Unsafe Conditions
Adverse Sea / Weather Conditions
Direct Causes- Unsafe Acts
Failure to Warn
Job Factors
Inadequate Leadership
Personal Factors
Inadequate Experience
Substandard Acts
Failure to follow procedure

Follow Up			
On	By	Follow Up	
Before & After Pictures			
Before	After		