

Vessel	Job ID	Assignor	Date Raised Date Completed	Job Description	Job Progress
BITX	125 11/2021	Vessel	22/Sep/2021 <b>Pending</b>	Oil spill on deck portside front of accommodation due to bunker line pipe leakage.	22/Sep/2021 (Gelu Antin   Staff Code - 10124 - MST) : Bunker pipe was temporary repaired by ship staff. Bunker line was tested after temporary repairs by ship staff.
BITX	124 10/2021	Vessel	21/Sep/2021 <b>23/Sep/2021</b>	Oil spill on deck portside front of accommodation due to bunker line leakage from a hole on pipe.	21/Sep/2021 (Gelu Antin   Staff Code - 10124 - MST) : Bunker pipe was temporary repaired.  21/Sep/2021 (Gelu Antin   Staff Code - 10124 - MST) : Bunker pipe was inspected and hole under the line founded.
BBLU	85 6/2021	Vessel	26/Aug/2021 <b>26/Aug/2021</b>	While entering in bosun store, a crew member was nearly to fall due to some grease on ladder step.	
BBLU	84 5/2021	Vessel	24/Aug/2021 <b>24/Aug/2021</b>	During fire, safety and security rounds, it was observed that some clothes are put on top of the laundry dryer machine while it is working.	
BBLU	60 4/2021	Vessel	10/Jul/2021 <b>10/Jul/2021</b>	During bunkering operation, a crew member noticed that the drain plug was not fixed on the bunker drip tray portside.	
VIVK	67 6/2021	Vessel	20/Jun/2021 <b>20/Jun/2021</b>	Near Miss Description (Please Mention The Event Chronologically)During inspection in pump room bilges one of the grating was not properly secured in pump room due to which the crewmember slipped & fell down, luckily he was not injured or had any major injury.	
VIVK	66 5/2021	Vessel	04/Aug/2021 <b>04/Aug/2021</b>	TEST	

BISK	56	Vessel	24/Jul/2021 24/Jul/2021	Crew member Slept on the Oily surface on Poop Deck	
BISK	55	Vessel	22/Jul/2021 23/Jul/2021	Observed crew member using power Cutting tools without Safety Goggle & Safety Gloves	
BISK	43	Vessel	04/Jul/2021 04/Jul/2021	Oftenly observed crewmembers are not removing their working gloves while entering accomodation & even using stairs in the accomodation, while opening latches of door.  All crewmembers called and explained them about wrong practice they are following, explained them about compromising vessels hygiene.	
BISK	42	Vessel	04/Jul/2021 04/Jul/2021	Recently while trying out Foam monitor, Foam monitor left unattended while water coming out from it & was locked, resulting monitor swining all directions	
BITX	107 8/2021	Vessel	22/Jun/2021 22/Jun/2021	Streeing gear and thermal boiler room doors found open while transiting HRA area of Gulf of Guinea.	
BITX	106 7/2021	Vessel	01/Jul/2021 02/Jul/2021	Lint not cleaned from dryer machines.	02/Jul/2021 (Nawin Khaware) : As a preventive measures, Ensure weekly accomodation rounds are adhered to strictly with special attention towards proper maintenance of ship's laundry and it's equipment.
BITX	105 6/2021	Vessel	01/Jul/2021 01/Jul/2021	Pump room entry reporting procedure not followed by one of the crew member prior entry.	
BBLU	58 3/2021	Vessel	17/Jun/2021 17/Jun/2021	WHILE BLOWING CARGO LINES, SUDDENLY THE CONNECTION WAS DISCONNECTED FROM THE AIR HOSE. THE CREW WHO IS PERFORMING THE JOB ALMOST GOT HIT BY THE PRESSURIZED AIR HOSE.	
BBLU	56	Vessel	11/Jun/2021 12/Jun/2021	Exit door aft block with mooring ropes	
BITX	103 4/2021	Vessel	04/Jun/2021 04/Jun/2021	Crew members observed going on monkey Island for hosing down without informing duty officer.	

ATLC	130 7/2021	Vessel	26/May/2021 <b>26/May/2021</b>	During the operation to increase vessel's security measures it was necessary to place razor wire around the vessel. During the execution of the job it was observed that some of the crew members did not use the appropriate gloves to handle the razor wire putting themselves in danger of injury due to nature of the wire.	
ATLC	129 6/2021	Vessel	23/May/2021 <b>23/May/2021</b>	While preparing the accomodation ladder Officer noticed that one A.B. was ready to come out at ship's gangway without wearing lifejacket.	
BBLU	55	Vessel	13/Apr/2021 <b>13/Apr/2021</b>	CHIEF COOK WAS SUDDEN SLIP DUE TO SLIPPERY SURFACE NEAR THE CO2 ROOM AND HE WAS NEARLLY TO FALL DOWN.	
ATLC	128 5/2021	Vessel	20/Apr/2021 <b>20/Apr/2021</b>	MAIN ENGINE OPERATING MANUAL WAS BEING USED BY ONE OF THE ENGINE ROOM PERSONAL WITH DIRTY HAND. IMMIDIATLY HE WAS STOPPED OF DOING SO AND INSTRUCTED THAT HE SHOULD HANDLE THE MANUALS WITH CLEAN HAND.	23/Jun/2021 (Stelian BOGHEA   Staff Code - 10166 - 2/E) : Instructed to all crew about handling manuals by clean hand.
ATLC	127 4/2021	Vessel	19/Apr/2021 <b>23/Apr/2021</b>	Thermometer on loading manifold are not working	13/Jul/2021 (Florin Bradatan   Staff Code - 10361 - C/OFF) : Thermometer on loading manifold changed and working satisfactory  23/Jun/2021 (Akshay Sadanand Gurav   Staff Code - 10235 - 3/OFF) : Manifold Thermometer replaced with new one
BBLU	54	Vessel	21/Mar/2021 <b>21/Mar/2021</b>	During heaving up of Recue boat to secure on board limit switch activating even the rescue boat still above the water level due to excessive old grease with dusk on the limit switch weight.	

BITX	79 3/2021	Vessel	21/Mar/2021 23/May/2021	DURING FIRE DRILL ONE FLASHLIGHT FROM FIREMAN'S OUTFIT WAS NOT ILLUMINATING, AFTER CHECKING THIS IS FOUND THAT THE FLASHLIGHT IS NOT RECHARGEABLE. ALL FIREMAN OUTFITS ARE EQUIPED WITH SAME FLASHLIGHTS. AND THERE IS NO FLASHLIGHTS ON BOARD TO BE REPLACED.	23/May/2021 (Ionut Gabriel Marsal   Staff Code - 10054 - C/OFF) : REQUISITION RECEIVED AT AGIOI THEODOROI ON 20 MAY 2021  26/Mar/2021 (Nawin Khaware) : Keep us closely posted once new Flashlights are available onboard. Meanwhile, if the existing flashlight are not rechargeable then can new set of battery be used for it's proper functioning. Please recheck and update here.  21/Mar/2021 (Vladislav Maluev   Staff Code - 10316 - 3/OFF) : REQUISITION RAISED FOR RECHARGEABLE FLASHLIGHT .
VIVK	47 2/2021	Vessel	17/Mar/2021 19/Mar/2021	During recent Discharging operations at Douala Port, ERES Terminal staff was engaged in Collecting cargo samples from COT without Donning Bitumen protective clothing and face shield.	19/Mar/2021 (Nawin Khaware) : All crew members must be reminded to wear proper PPE for the type of work they are engaged in.
BITX	78 2/2021	Vessel	07/Mar/2021 15/Mar/2021	JOT System	
BBLU	53	Vessel	14/Mar/2021 19/Mar/2021	Empty boxes are left unattended near the entrance door. Crew member entered the alleyway and his leg was stocked on the boxes and lost his balance nearly fall down, luckily he manage to hold the hand rail.	19/Mar/2021 (Nawin Khaware) : Please ensure all crew must be briefed on maintaining proper housekeeping on ship and keep the passage clear from all obstructions.
ATLC	114	Vessel	16/Feb/2021 23/Feb/2021	Engine room crew was observed not wearing safety helmets and safety glasses while in engine room and carrying out maintenance. The crew was briefed on the important aspects of personal safety and company policy requirements. All have been briefed to ensure adherence of wearing proper PPE while in Engine Room.	24/Jun/2021 (Ashwini Kumar   Staff Code - 10326 - 2/E) : Engine crew instructed to wear proper PPE while doing maintenance routine. The crew also briefed about personal safety and company policies.
BITX	77 1/2021	Vessel	09/Feb/2021 16/Feb/2021	During Lome anchorage, one of the crew member walking on dseck without helmet.	15/Feb/2021 (Tsanko Yordanov Tsankov   Staff Code - 10328 - MST) : Crew was instructed to wear and use a proper PPE
BBLU	52	Vessel	14/Feb/2021 16/Feb/2021	Due to rolling of the vessel water tight door which was not locked properly, got a sudden bang. While one of the crew member try to closed it, nearly get caught of the opening / closing door.	17/Feb/2021 (MAXIMILIAN LUMANGLAS   Staff Code - 10131 - MST) : Training / demonstration carried out for proper / closing of watertight door.

BBLU	51 1/2021	Vessel	13/Feb/2021 Pending		19/Mar/2021 (Nawin Khaware) : This was a test report o verify if system is functioning properly.  03/Mar/2021 (Rakesh Kumar) : The Near Miss is not reflected for which the Cause/Corrective Action and Preventive Action has been displayed.
VIVK	46 1/2021	Vessel	10/Feb/2021 11/Feb/2021	DURING DISCHARGING OPERATION AT DOUALA UPON COMPLETION OF DISCHARGING OPERATION AFTER DISCONNECTING THE HOSE FROM SHORE SIDE TERMINAL PERSONNELS DID NOT TIGHTEN THE HOSE BLANK PROPERLY AS A RESULT OF WHICH WHILE PICKING UP THE HOSE DROPS OF BITUMEN STARTED TO COME OUT OF THE HOSE.	11/Feb/2021 (Nawin Khaware) : Office Dept has been changed from "General" to "Safety".
ATLC	112	Vessel	06/Jan/2021 08/Jan/2021	Auxiliary Engine No.3 T/C overhaul was planned . The task was being undertaken alongwith the Ship's Fitter. The Fitter commenced dismantling of the TC without confirming Isolations for Lube Oil System and Engine starting. CE noticed the same and stopped the unsafe task, briefed the fitter on the importance of isolations for personal and machinery safety. The task was undertaken again after confirming isolations in place. A Safety stand down was conducted with Engineers and Crew to ensure procedures are in place for all maintenance tasks and every task is carried out with a brief toolbox meeting with the team to avoid re-occurrence.	08/Jan/2021 (Ajay Kumar .   Staff Code - 10320 - C/E) : All Engineers and crew briefed.
ATLC	111	Vessel	12/Nov/2020 12/Nov/2020	Observed Burning smell coming in the Accommodation A/C , Asked Duty A/B to Check for fire Rounds, found in "A" deck Toilet paeprs were burning in Garbage bin due to Cigarettes Buds inside the Bin.	
ATLC	77 7/2020	Vessel	24/Apr/2020 24/Apr/2020	It was observed that after one hour of discharging operation suddenly one of the Cargo hose (No.3) started leaking. About half litre of Bitumen was leaked on deck. Chief Officer was informed and discharging operation was ceased.	
BISK	39 3/2020	Vessel	28/Apr/2020 06/May/2020	One crew member was found to be using power tool for descaling without eye protection on the main deck.	
ATLC	73 4/2020	Vessel	21/Mar/2020 21/Mar/2020	11101 Operating instructions for Lifeboat STBD not readable	

ATLC	72 3/2020	Vessel	20/Mar/2020 20/Mar/2020	07124 Fire hose of Fire Hydrant at forcastle found leaking from a small hole during Emergency Fire Pump pressure test	<p>21/Mar/2020 (Rakesh Kumar) : Port State has confirmed the observations as rectified in the report issue.</p> <p>21/Mar/2020 (Rakesh Kumar) : Port State has confirmed the observations as rectified in the report issue.</p> <p>21/Mar/2020 (Rakesh Kumar) : Port State has confirmed the observations as rectified in the report issue.</p> <p>21/Mar/2020 (Rakesh Kumar) : Port State has confirmed the observations as rectified in the report issue.</p> <p>21/Mar/2020 (Rakesh Kumar) : Port State has confirmed the observations as rectified in the report issue.</p> <p>21/Mar/2020 (Rakesh Kumar) : Port State has confirmed the observations as rectified in the report issue.</p> <p>21/Mar/2020 (Rakesh Kumar) : Port State Control in its report has marked this as rectified.</p> <p>21/Mar/2020 (Rakesh Kumar) : Port State Control in its report has marked this as rectified.</p> <p>21/Mar/2020 (Rakesh Kumar) : Port State Control in its report has marked this as rectified.</p> <p>21/Mar/2020 (Rakesh Kumar) : Port State Control in its report has marked this as rectified.</p> <p>21/Mar/2020 (Rakesh Kumar) : Port State Control in its report has marked this as rectified.</p> <p>21/Mar/2020 (Rakesh Kumar) : Port State Control in its report has marked this as rectified.</p> <p>21/Mar/2020 (Rakesh Kumar) : Port State Control in its report has marked this as rectified.</p> <p>21/Mar/2020 (Rakesh Kumar) : Port State Control in its report has marked this as rectified.</p> <p>21/Mar/2020 (Gelu Antin &lt;br/&gt; Staff Code - 10124 - MST) : Hose removed and replaced with new one</p>
------	--------------	--------	----------------------------	-----------------------------------------------------------------------------------------------------------------------	---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

ATLC	71 2/2020	Vessel	20/Mar/2020 21/Mar/2020	07199 Pieces of insulation was missing to Emergency Diesel Generator exhaust gas elbow pipe (approx. 40 cm) and to Thermal Boiler Room Aft PS two pieces of insulation missing from steam pipes	21/Mar/2020 (Gelu Antin   Staff Code - 10124 - MST) : Pipes were insulated as requested.
ATLC	70 1/2020	Vessel	20/Mar/2020 21/Mar/2020	14501 All type of garbage found on poop deck. To be delivered to shore facilities. Receipt to be submitted to PSCO Piraeus Office.	<p>21/Mar/2020 (Rakesh Kumar) : Garbage was landed on 21st at Piraeus</p> <p>21/Mar/2020 (Rakesh Kumar) : Garbage was landed on 21st at Piraeus</p> <p>21/Mar/2020 (Rakesh Kumar) : Garbage was landed on 21st at Piraeus</p> <p>21/Mar/2020 (Rakesh Kumar) : Garbage was landed on 21st at Piraeus</p> <p>21/Mar/2020 (Rakesh Kumar) : Garbage was landed on 21st at Piraeus</p> <p>21/Mar/2020 (Rakesh Kumar) : Garbage was landed on 21st at Piraeus</p> <p>21/Mar/2020 (Gelu Antin &lt;br/&gt; Staff Code - 10124 - MST) : All garbage discharged on 21-Mar-2020 and invoice sent to Agents to be forwarded to PSC Piraeus</p>