

# Maritec Tanker Management Private Limited

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

#### **Non Conformance Details**

Vessel: Bahama Blue	Defect ID: 212	NCR # : 2/2024	Is NCR ?: Yes
---------------------	----------------	----------------	---------------

#### **Defect Details**

During USCG Inspection, it was noticed that Lifeboat engine was not going on astern movement due issues in engine clutch in system.

Requisition Code:

Categories					
Primary :	LSA/FFA	Inspector - Internal :		Vessel Dept:	Engine
Secondary :	Life Saving Appliances	Inspector External :		Office Dept:	Safety
		Inspection Date :	07-Apr-2024		

#### **Applicable Dates**

Date Raised: 08-Apr-2024 ETC: 15-Apr-2024 Date Completed:

Other Details		
Priority : Urgent	Assigned By: Port State Control	Verified By :
Display in Daily Meeting? : No	SFI:	Verified On:

# Causes

General wear & tier of L/B engine clutch in system.

#### **Corrective Action**

L/B Engine gear box was opened up and observed that ahead gear was stucked with clutch. Same was freed up, system fitted back in place and engine tried out, L/B engine found working satisfactory. Same was reported to Class RINA,USCG and to DPA.

# **Preventive Action**

PMS routines for L/B engine and associated gears to be carried out diligently. C/E and Safety officer must ensure L/B engine is maintained in good working condition all the time. Weekly routines for L/B engines to be completed regularly.

### **CONTRIBUTING FACTORS**

#### Follow Up

On	Ву	Follow Up	
09/Apr/2024	Petre Aboyan   Staff Code - 10603 - MST	Gear box disembelled, Clutch cone removed, lapping done of wear, general cleaning of gear box done, new oil refilled. Engine tried out in Ahead, Neutral and Astern direction. All in good working order	Link1 Link2

# **Before & After Pictures**

Before	After

Non Conformance Details Printed On: 10-May-2024 1/2







