



# Maritec Tanker Management

## Non Conformance Details

Ship File No : N/A  
Office File No : N/A  
Form No : N/A  
Issue : N/A  
Revision : N/A  
Rev Date : N/A

Vessel : Demerara	Defect ID : 59	NCR # : 2/2023	Is NCR ? : Yes
-------------------	----------------	----------------	----------------

### Defect Details

Lifeboat air bottle charge hose not available onboard

Requisition Code :

### Categories

Primary :	LSA/FFA	Inspector - Internal :	Fiacre Fonseca	Vessel Dept :	Deck
Secondary :	Life Saving Appliances	Inspector External :		Office Dept :	Technical
		Inspection Date :	14-Jan-2023		

### Applicable Dates

Date Raised : 14-Jan-2023	ETC : 15-Apr-2023	Date Completed : 19-May-2023
---------------------------	-------------------	------------------------------

### Other Details

Priority : Urgent Defect deferred to DD	Assigned By : Ops Suptd	Verified By :
Display in Daily Meeting? : No	SFI :	Verified On :

### Causes

Missing on ship's delivery

### Corrective Action

PR done - waiting for delivery

### Preventive Action

Spare to be delivered in due time

### Applicable Tags

### Descriptions

Others

### Root Causes- Job Factor

Inadequate Leadership and / or Supervision

### Root Causes- Management Factors

Inadequate Monitoring / Supervision

### Root Causes- Personal Factor

Inadequate Communication

**Direct Causes- Unsafe Acts**

Improper Position for Task

**Personal Factors**

Lack of Knowledge

**Follow Up**

On	By	Follow Up	
18/May/2023	Gelu Antin   Staff Code - 10124 - MST	Lifeboat air bottle charge hose is available, but is necessary a couple connection in order to be use. GS issued and waiting spare parts.	<a href="#">Link1</a>
29/Mar/2023	Adrian Tudor   Staff Code - 10513 - MST	Waiting for spare parts - PR done	
27/Jan/2023	Fiacre Fonseca		

**Before & After Pictures**

Before	After
--------	-------