



Maritec Tanker Management Private Limited

Non Conformance Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Biskra	Defect ID : 198	NCR # : 10/2024	Is NCR ? : Yes
-----------------	-----------------	-----------------	----------------

Defect Details

Air leak on engine room funnel dampers.

Requisition Code :

Categories

Primary :	E/R Machinery	Inspector - Internal :		Vessel Dept :	Engine
Secondary :	Miscellaneous	Inspector External :		Office Dept :	Technical
		Inspection Date :	18-Apr-2023		

Applicable Dates

Date Raised : 18-Apr-2023	ETC : 18-Apr-2023	Date Completed : 20-Apr-2023
---------------------------	-------------------	------------------------------

Other Details

Priority : Urgent	Assigned By : Port State Control	Verified By : Nawin Khaware
Display in Daily Meeting? : No	SFI :	Verified On : 05/Jul/2024

Causes

Inadequate maintenance and irregular checks as per company procedures.

Corrective Action

Derusting, coating and repair of affected area as required.

Preventive Action

proper maintenance and regular should be maintain at all time as per company procedures.

CONTRIBUTING FACTORS

Descriptions

Machinery / Equipment Damage

Root Causes- Job Factor

Inadequate Maintenance

Job Factors

Inadequate Maintenance or Not Done as per Manufacturer's Schedules

Follow Up

On	By	Follow Up	
Before & After Pictures			
Before		After	