



Maritec Tanker Management Private Limited

Non Conformance Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Biskra	Defect ID : 197	NCR # : 9/2024	Is NCR ? : Yes
-----------------	-----------------	----------------	----------------

Defect Details

Thermal oil heating pipe lagging missing on port side main deck.

Requisition Code :

Categories

Primary :	Cargo Handling	Inspector - Internal :		Vessel Dept :	Deck
Secondary :	Cargo Measuring/ Test Equipment	Inspector External :		Office Dept :	Technical
		Inspection Date :	18-Apr-2023		

Applicable Dates

Date Raised : 18-Apr-2023	ETC : 18-Apr-2023	Date Completed : 20-Apr-2023
---------------------------	-------------------	------------------------------

Other Details

Priority : Normal	Assigned By : Port State Control	Verified By : Nawin Khaware
Display in Daily Meeting? : No	SFI :	Verified On : 05/Jul/2024

Causes

Inadequate maintenance.

Corrective Action

The heating pipe will be properly covered with lagging and alluminium sheet.

Preventive Action

Proper maintenance will be carried out under adequate supervision.

CONTRIBUTING FACTORS

Descriptions

Injury

Root Causes- Job Factor

Inadequate Maintenance

Job Factors

Inadequate Maintenance or Not Done as per Manufacturer's Schedules

Follow Up

On

By

Follow Up

Before & After Pictures

Before

After