

Maritec Tanker Management Private Limited

Ship File No : N/A Office File No : N/A Form No : N/A Issue : N/A Revision : N/A

Rev Date

Non Conformance Details

Vessel : Bitu Express Defect ID : 321 NCR # : 3/2023 Is NCR ? : Yes

Defect Details

Code 10109 - Search Light Foundation bolts were tightened during PSC Inspection at Tutunciftlik, Turkey.

Requisition Code:

Categories							
Primary :	Nav/Comm	Inspector - Internal:		Vessel Dept:	Deck		
Secondary :	Navigation Equipment	Inspector External :		Office Dept:	Operations		
		Inspection Date :	20-Nov-2023				

Applicable Dates

Other Details

Priority : Normal	Assigned By: Port State Control	Verified By: Nawin Khaware
Display in Daily Meeting? : No	SFI:	Verified On: 08/Apr/2024

Causes

Search Light Bolts were found tightened during PSC Inspection. It was tightened by Ship's ETO one day before at anchorage area due to very bad weather conditions, wind over 40 knts, in order to prevent any damage and even loose of search light if bolts were free of moving.

Corrective Action

Observation was rectified during Inspection on the same day. Bolts were loosen to have free movement of Search Light.

Preventive Action

Accurate Inspection on all deck and engine areas before Ship entering in the port.

CONTRIBUTING FACTORS

Follow Up

0.5	Des	Fallery He	
On	Бу	Follow Up	

Non Conformance Details Printed On: 28-Jun-2024 1/2

24/Nov/2023

Ankur Kumar
Staff Code - 10378 - 3/OFF

Search Light Bolts was found tightened during PSC inspection at TUTUNCIFTLIK, TURKEY. It was tightened by Ship's ETO one day before at anchorage area due to very bad weather conditions, wind over 40 Knts in order to prevent any damage and even loose of search light if bolts were free of maying. bolts were free of moving.

This observation was rectified during inspection on the

same day.

Link1 Link2

Link3

Link4 Link5

Link6

Link7 Link8

Link9

Before & After Pictures

Before









After







