

Maritec Tanker Management Private Limited

Ship File No : N/A Office File No : N/A Form No : N/A Issue : N/A Revision : N/A

Rev Date

Non Conformance Details

Vessel: Bitu Express Defect ID: 340 NCR #: 5/2024 Is NCR ?: Yes

Defect Details

Hole Observed on PV Valve Mesh 2 Stbd During PSC Inspection

Requisition Code:

Categories						
Primary :	Dk Machinery	Inspector - Internal :		Vessel Dept:	Deck	
Secondary :	Deck Equipment	Inspector External :		Office Dept:	Technical	
		Inspection Date :				

Applicable Dates

Date Raised: 25-Mar-2024 ETC: 10-Apr-2024 Date Completed: 25-Mar-2024

Other Details

Priority: Normal Assigned By: Vessel Verified By: Nawin Khaware

Display in Daily Meeting?: No SFI: Verified On: 08/Apr/2024

Causes

General wear & tier. Lack of supervision.

Corrective Action

PV valve wire mesh for 2 (S) COT has been renewed in front of Inspector.

Preventive Action

PMS routines for all PV Valve for integrity of wire mash to be carried out regularly. Operation of PV valves must be tested prior each operation.

CONTRIBUTING FACTORS

Root Causes- Job Factor

Inadequate Leadership and / or Supervision

Inadequate Maintenance

Root Causes- Management Factors

Inadequate Monitoring / Supervision

Direct Causes- Unsafe Acts

Failure to Follow Repair / Maintenance Instructions

Non Conformance Details Printed On: 28-Jun-2024 1/3

Job Factors

Wear and Tear (Not Related to Lack of Maintenance)

Follow Up

On	Ву	Follow Up	
08/Apr/2024	Nawin Khaware	ETC has been changed from "31 Mar 2024" to "10 Apr 2024".	
01/Apr/2024	Marin Panait Staff Code - 10017 - MST	Instructed Pumpman during inspection, was replaced accordingly.	Link1 Link2 Link3 Link4 Link5 Link6

Before & After Pictures

Before









File Not Uploaded



Notification



File Not Uploaded



Notification



File Not Uploaded



Notification



File Not Uploaded



Notification



File Not Uploaded