

Maritec Tanker Management Private Limited

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Non Conformance Details

Vessel: Bitu Atlantic Defect ID: 325 NCR #: 4/2024 Is NCR ?: Yes

Defect Details

Fire Alarm Control panel on bridge presents failure message regarding to loop 1 which governs the entire fire detectors of accommodation, exemption and flag status regarding mentioned observation also submitted during inspection.

Requisition Code:

Categories						
Primary :	LSA/FFA	Inspector - Internal:	Nawin Khaware	Vessel Dept:	Engine	
Secondary :	Fire Fighting Appliances	Inspector External :		Office Dept:	Safety	
		Inspection Date :	30-Mar-2024			

Applicable Dates

Date Raised: 30-Mar-2024 ETC: 30-Apr-2024 Date Completed: 10-Apr-2024

Other Details					
Priority : Urgent	Assigned By: Terminal Inspector	Verified By: Nawin Khaware			
Display in Daily Meeting? : No	SFI:	Verified On: 14/May/2024			

Causes

Wear & Tier.

Corrective Action

Reported to Manufacturer, Technician had attended the vessel & issues were resolved. It was observed that Technician had made wrong connection in the panel while previous technician had attended the vessel at last port.

Preventive Action

Regular maintenance of FFA items to be carried out properly. Fire alarm system must be tried out as per PMS routines.

CONTRIBUTING FACTORS

Descriptions

Machinery / Equipment Damage

Root Causes- Management Factors

Problem Identification / Control Issue

Job Factors


Inadequate Planning

Non Conformance Details Printed On: 14-May-2024 1/2

On By Follow Up 13/Apr/2024 Gelu Antin
Staff Code - 10124 - MST SHORE TECHNICIAN ATTENDED AT VESSEL AND REPAIR IT. AFTER THAT CLASS REMOTE SURVEY CARRIED OUT FULLY LIVESTREAMING FOR VERIFICATION. PRESENTLY FIRE DETECTION SYSTEM IS OPERATIONAL IN ALL RESPECT. Link1 Link2

Before & After Pictures

Before



After

