



# Maritec Tanker Management

## Near Miss Details

Ship File No : N/A  
Office File No : N/A  
Form No : N/A  
Issue : N/A  
Revision : N/A  
Rev Date : N/A

### Guidance:

- 01) Please do not mention any names in the near miss report.
- 02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet.
- 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel : Asphalt Teranga

Defect ID : 147

### Defect Details

while taking rounds I observed resuce boat engine fuel hose was broken leaking the fuel. Same renewed the hose and tested found working satisfactory.

Requisition Code :

### Categories

Primary :

Near Miss

Vessel Dept :

Deck

Secondary :

Other

Office Dept :

Technical

### Applicable Dates

Date Raised : 01-Jun-2023

Date Completed : 01-Jun-2023

### Other Details

Priority :

Normal

QMS Elements Ref :

- SELECT -

Verified By :

Show in Monthly Safety Meeting? :

No

SFI :

Verified On :

Potential to become a serious accident : Low

Recurrence : Low

### Causes

### Corrective Action

### Preventive Action

### Applicable Tags

### Follow Up

On

By

Follow Up

### Before & After Pictures

Before

After