



Maritec Tanker Management

Near Miss Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Guidance:

- 01) Please do not mention any names in the near miss report.
- 02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet.
- 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel : Asphalt Teranga

Defect ID : 147

Defect Details

while taking rounds I observed resuce boat engine fuel hose was broken leaking the fuel. Same renewed the hose and tested found working satisfactory.

Requisition Code :

Categories

Primary :

Near Miss

Vessel Dept :

Deck

Secondary :

Other

Office Dept :

Technical

Applicable Dates

Date Raised : 01-Jun-2023

Date Completed : 01-Jun-2023

Other Details

Priority :

Normal

QMS Elements Ref :

- SELECT -

Verified By :

Show in Monthly Safety Meeting? :

No

SFI :

Verified On :

Potential to become a serious accident : Low

Recurrence : Low

Causes

Corrective Action

Preventive Action

Applicable Tags

Follow Up

On

By

Follow Up

Before & After Pictures

Before

After