

# Maritec Tanker Management

### **Near Miss Details**

Ship File No : N/A Office File No : N/A Form No : N/A Issue : N/A Revision : N/A

: N/A

Rev Date

Guidance:

01) Please do not mention any names in the near miss report.

02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet. 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel: Asphalt Teranga Defect ID: 136

#### **Defect Details**

When casting off from the terminal and tug was pulling the vessel one crew member was observe standing in the snap back zone.

Requisition Code:

Categories						
Primary :	Near Miss	Vessel Dept :	Deck			
Secondary:	Lack of Situational Awareness	Office Dept:	Safety			

#### **Applicable Dates**

Date Raised: 01-Mar-2023 Date Completed: 11-Mar-2023

#### Other Details

Priority :	Normal	QMS Elements Ref :	- SELECT -	Verified By :	Nawin Khaware
Show in Monthly Safety Meeting? :	No	SFI:		Verified On:	13/Mar/2023

Potential to become a serious accident: Medium Recurrence: Low

## Causes

Lack of knowledge about safe mooring procedures.

#### **Corrective Action**

He was immediately informed to keep clear away from the area. Furthermore demonstrate about the consequences behind that scheme carried out and advise always to keep away from the snap back zone safety conscious and for more detailed also go back and watch the mooring videos on videotel.

#### **Preventive Action**

All staff were reminded to follow safe mooring procedures and always stay clear from snap back zone.

# **Applicable Tags**

#### **Root Causes- Management Factors**

Inadequate Monitoring / Supervision

#### **Root Causes- Personal Factor**

Lack of Skill

Near Miss Details Printed On: 12-Sep-2023 1/2

Direct Causes- Unsafe Acts							
Failure to Follow Rules and Regulations							
Job Factors							
Inadequate Supervision							
Personal Factors							
Lack of Skill							
Substandard Acts							
Failure to follow procedure							
Improper Position for Task							
Follow Up							
On	Ву	Follow Up					
Before & After Pictures							
Before			After				

Near Miss Details Printed On: 12-Sep-2023 2/2