

Maritec Tanker Management Near Miss Details

Ship File No : N/A Office File No : N/A Form No : N/A Issue : N/A Revision : N/A

: N/A

Rev Date

Guidance:

01) Please do not mention any names in the near miss report.

02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet. 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel: Asphalt Teranga Defect ID: 140

Defect Details

AFTER VESSLE CAST OFF FROM PORT UNDERWAY ONE CREW WAS FOUND SECURING CRANE WIRE ON DECK WITHOUT SAFETY HARNESS

Requisition Code:

Categories				
Primary :	Near Miss	Vessel Dept :	Deck	
Secondary :	Safe Working Procedures not Followed	Office Dept:	Safety	

Applicable Dates

Date Raised: 04-Apr-2023 Date Completed: 10-Apr-2023

	Other Details	Other Details					
	Priority :	Normal	QMS Elements Ref :	- SELECT -	Verified By :	Nawin Khaware	
	Show in Monthly Safety Meeting? :	No	SFI:		Verified On:	13/Apr/2023	
Potential to become a serious accident : Low		Recurrence : Low					

Causes

Lack of knowledge/ Negligence

Corrective Action

THE CREW WAS IMMEDIATELY CALLED DOWN AND WAS INSTRUCTED TO USE SAFETY HARNESS AND ALWAYS FOLLOW SAFE WORKING PROCEDURES

Preventive Action

All crew were advised to follow COSWP, emphsis were given on use of PPE items.

Applicable Tags

Root Causes- Job Factor

Inadequate Work Standards

Root Causes- Management Factors

Inadequate Monitoring / Supervision

Near Miss Details Printed On: 08-Sep-2023 1/2

Root Causes- Personal Factor Lack of Knowledge

Lack of Skill

Direct Causes- Unsafe Acts

Failure to Use PPE Properly

Personal Factors

Lack of Knowledge

Substandard Acts

Failing to use PPE properly

Failure to observe basic safety rules

Follow Up

On	Ву	Follow Up	
13/Apr/2023	Nawin Khaware	Concur with corrective and preventive measures.	

Before & After Pictures

Before	After

Near Miss Details Printed On: 08-Sep-2023 2/2