



Maritec Tanker Management

Near Miss Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Guidance:

- 01) Please do not mention any names in the near miss report.
- 02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet.
- 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel : Bahama Blue

Defect ID : 139

Defect Details

During monthly routine check / inspection / greasing of deck cargo hose crane found that the crane wire part in between the crane hook and the block / weight not in good condition and observed to be corroded. The block / weight believed to be too heavy for the size of the wire as it gave too much tension to affected part when lifting up load. Also the crane hook part that make it rotate freely painted and not rotating at all.

Requisition Code :

Categories

Primary :	Near Miss	Vessel Dept :	Deck
Secondary :	Inadequate Maintenance / Wear and Tear	Office Dept :	Technical

Applicable Dates

Date Raised : 05-Dec-2022

Date Completed : 07-Dec-2022

Other Details

Priority :	Urgent	QMS Elements Ref :	- SELECT -	Verified By :	
Show in Monthly Safety Meeting? :	No	SFI :		Verified On :	
Potential to become a serious accident : Medium			Recurrence : Medium		

Causes

Corroded wire part.

Corrective Action

Replaced with new spare wire. Maintenance carried out to the hook.

Preventive Action

Proper Maintenance and lubrication and follow maintenance schedules.
To maintain with oil or grease the hook part that make it rotate freely.
Avoid painting the hook part make it rotate freely.

Applicable Tags

Follow Up

On	By	Follow Up	
----	----	-----------	--

Before & After Pictures

Before



After

