

Guidance: 01) Please do not mention any names in the near miss report. 02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet. 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.									
Vessel: Bitu Atlantic				Defect ID : 112					
Defect Details									
commenced dismantlin and stopped the unsafe undertaken again after	ng of the TC w e task, briefed confirming iso	vithout confirming I the fitter on the olations in place	g Isolations importance . A Safety st	being undertaken alongwith for Lube Oil System and En- of isolations for personal ar tand down was conducted w k is carried out with a brief to	gine starting. CE nd machinery safe vith Engineers and	noticed the same ety. The task was d Crew to ensure			
Requisition Code :									
Categories									
Primary :	Near Mis	Near Miss		Dept :	Engine				
Secondary :		Lack of Situational Awareness		Dept :	Safety				
Applicable Dates									
Date Raised : 06-Jan-2021				Date Completed : 08-Jan-2021					
Other Details									
Priority :	Normal	QMS Elements Ref :		M. 2.20 - Near Miss Report	Verified By :				
Show in Monthly Safety Meeting? :	No	SFI :			Verified On :				
Potential to become a serious accident : Low				Recurrence : Low					
Causes									
Lack of knowledge.									
Corrective Action									
Unsafe act was immediately stopped by Senior Engineer.									
Preventive Action									
Meeting was held with all members and discussed regarding importance of Lock out/Tag out.									
Applicable Tags									
Follow Up									
On	Ву	By Follow Up							

08/Jan/2021	Ajay Kumar . Staff Code - 10320 - C/E	All Engineers and	crew briefed.					
Before & After Pictures								
Before			After					