



# Maritec Tanker Management Private Limited

## Near Miss Details

Ship File No : N/A  
Office File No : N/A  
Form No : N/A  
Issue : N/A  
Revision : N/A  
Rev Date : N/A

### Guidance:

- 01) Please do not mention any names in the near miss report.
- 02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet.
- 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel : Kensington LG

Defect ID : 19

### Defect Details

During weekly inspection was found that the Lifebuoy line snafued by wind around the lifebuoy stowage position.

Requisition Code :

### Categories

Primary :	Near Miss	Vessel Dept :	Deck
Secondary :	Lack of Supervision / Leadership / Planning	Office Dept :	Safety

### Applicable Dates

Date Raised : 07-Sep-2023

Date Completed : 13-Sep-2023

### Other Details

Priority :	Normal	QMS Elements Ref :	- SELECT -	Verified By :	Nawin Khaware
Show in Monthly Safety Meeting? :	No	SFI :		Verified On :	06/Oct/2023

Potential to become a serious accident : Low

Recurrence : Low

### Causes

Lack of safety rounds.

### Corrective Action

Lines were made clear and ensured it's maintained in the state of readiness all the time.

### Preventive Action

All the safety equipment must be maintained in the state of readiness all the time.

### CONTRIBUTING FACTORS

#### Root Causes- Job Factor

Inadequate Purchasing

#### Direct Causes- Unsafe Conditions

Inadequate Guards or Barriers

#### Job Factors

Inadequate Work Standards

Follow Up

On

By

Follow Up

Before & After Pictures

Before

After