



## Maritec Tanker Management

### Near Miss Details

Ship File No : N/A  
Office File No : N/A  
Form No : N/A  
Issue : N/A  
Revision : N/A  
Rev Date : N/A

#### Guidance:

- 01) Please do not mention any names in the near miss report.
- 02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet.
- 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel : Bahama Blue

Defect ID : 140

#### Defect Details

While vessel approaching the terminal anchorage at slow speed during the night ( 2100 HLT 08.01.2023 ) , Sighted numerous unlit small supply boats anchored at the location where vessel will be anchoring for cargo operation. Momentarily stopped the vessel, use the whistle and search light to call the attention of the supply boats and wait until they clear the location. After all clear, vessel approach the terminal anchorage and safely anchored.

Requisition Code :

#### Categories

Primary :	Near Miss	Vessel Dept :	Deck
Secondary :	Other	Office Dept :	Safety

#### Applicable Dates

Date Raised : 09-Jan-2023

Date Completed : 15-Jan-2023

#### Other Details

Priority :	Normal	QMS Elements Ref :	- SELECT -	Verified By :	Nawin Khaware
Show in Monthly Safety Meeting? :	No	SFI :		Verified On :	20/Jan/2023
Potential to become a serious accident : Medium			Recurrence : Medium		

#### Causes

unlit supply boats anchored in terminal anchorage

#### Corrective Action

Always approach with caution at safe speed.

#### Preventive Action

1. Proper lookout at all times.
2. Awareness off the situation.
3. Warning / Notices on ENC / ECDIS chart.

#### Applicable Tags

#### Descriptions

Others

#### Root Causes- Personal Factor

Situational Awareness

**Direct Causes- Unsafe Conditions**

Substandard Port and Berthing Facilities

**Follow Up**

**On**

**By**

**Follow Up**

**Before & After Pictures**

**Before**

**After**