

Maritec Tanker Management

Near Miss Details

Ship File No : N/A Office File No : N/A Form No : N/A Issue : N/A Revision : N/A

: N/A

Rev Date

Guidance:

01) Please do not mention any names in the near miss report.

02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet.
03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel: Bitu River Defect ID: 2

Defect Details

A crew member received minor heat burns while taking soundings from ER Service and settling tanks. It was observed that the location of the sounding pipes was awkward and in addition thermal oil hot system lines were passing across the access. Since the task is daily routines the crew member has been advised to take adequate precautions to avoid any burns or injury, to wear correct and full PPE while undertaking the task and keep a person standby.

Requisition Code:

Categories						
Primary :	Near Miss	Vessel Dept :	Engine			
Secondary :	Inadequte Engineering /Design	Office Dept:	Technical			

Applicable Dates

Date Raised: 09-Nov-2022 Date Completed: 09-Nov-2022

Other Details							
Priority :	Normal	QMS Elements Ref :	- SELECT -	Verified By :			
Show in Monthly Safety Meeting? :	No	SFI:		Verified On:			
Potential to become a serious accident : Low			Recurrence : Low				

Causes

Corrective Action

Preventive Action

Applicable Tags

Root Causes- Job Factor

Inadequate Work Standards

Root Causes- Management Factors

Inadequate Training

Root Causes- Personal Factor

Situational Awareness

Near Miss Details Printed On: 07-Dec-2022 1/2

Direct Causes- Unsafe Acts							
Failure to Use PPE Properly							
Job Factors							
Inadequate Work Standards							
Substandard Acts							
Failing to use PPE properly							
Follow Up							
On	Ву	Follow Up					
Before & After Pictures							
Before		After					

Near Miss Details Printed On: 07-Dec-2022 2/2