



Maritec Tanker Management

Near Miss Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Guidance:

- 01) Please do not mention any names in the near miss report.
- 02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet.
- 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel : Demerara

Defect ID : 76

Defect Details

On his daily routine on deck, Chief Officer in order to verify that all life buoys were properly placed in position noticed that on a life buoy from poop deck, the life line was not properly attached. The life line was fastened on the grabbing rope of the life buoy instead of the life buoy itself.

Requisition Code :

Categories

Primary :	Near Miss	Vessel Dept :	Deck
Secondary :	Lack of Knowledge / Skill	Office Dept :	Safety

Applicable Dates

Date Raised : 11-Apr-2023

Date Completed : 11-Apr-2023

Other Details

Priority :	Normal	QMS Elements Ref :	- SELECT -	Verified By :	Nawin Khaware
Show in Monthly Safety Meeting? :	No	SFI :		Verified On :	26/May/2023
Potential to become a serious accident : Low			Recurrence : Low		

Causes

Lack of training or familiarization, Lack of skills, Lack of proper monitoring

Corrective Action

Thorough inspection to be carried out by a responsible officer in order to verify the readiness of the equipment which was previously inadequately attached.

Preventive Action

Case will be discussed during the forthcoming Safety Committee Meeting for awareness.

Applicable Tags

Root Causes- Management Factors

Inadequate Procedures / Checklists

Direct Causes- Unsafe Acts

Incorrect Use of Equipment or Machinery

Job Factors			
Inadequate Work Standards			
Personal Factors			
Inadequate Experience			
Follow Up			
On	By	Follow Up	
Before & After Pictures			
Before		After	