

Maritec Tanker Management Near Miss Details

Ship File No : N/A Office File No: N/A Form No : N/A : N/A Issue

Revision : N/A Rev Date : N/A

01) Please do not mention any names in the near miss report.

02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet. 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel: Bitu Atlantic Defect ID: 181

Defect Details

One of the engine crew was cleaning Aux. Eng auto backwash filter without depressurizing when open the cover, hot fuel immediately come out

Requisition Code:

Categories						
Primary:	Near Miss	Vessel Dept :	Engine			
Secondary :	Procedures not Followed	Office Dept:	Crew			

Applicable Dates

Date Raised: 11-Mar-2022 Date Completed: 11-Mar-2022

Other Details	s
---------------	---

Priority :	Normal	QMS Elements Ref :	- SELECT -	Verified By :	
Show in Monthly Safety Meeting?:	No	SFI:		Verified On:	
B + 4 1 + 1					

Potential to become a serious accident: Low Recurrence : Low

Causes

Unawarenness of dangerous associated with pressurized line

Corrective Action

Office concure whith ship immediate action and the same time would like to temaind ship staf to take a session on damages associated with job planed to undertake on pressurized line.

Preventive Action

Before opening it must be depressurized and drained

Applicable Tags

Descriptions

Others

Root Causes- Job Factor

Inadequate Work Standards

Near Miss Details Printed On: 02-Apr-2022 1/2

Root Causes- Management Factors							
Others							
Root Causes- Personal Factor							
Lack of Skill	Lack of Skill						
Direct Causes- Uns	Direct Causes- Unsafe Conditions						
Others							
Direct Causes- Uns	afe Acts						
Failure to Use PPE P	Failure to Use PPE Properly						
Job Factors							
Inadequate Planning	Inadequate Planning						
Personal Factors							
Lack of Skill							
Substandard Acts							
Lifting, Handling or Storing Incorrectly							
Substandard Conditions							
Hazardous Environmental Condition							
Follow Up							
On	Ву	Follow Up					
Before & After Pictures							
Before			Δfter				