

Maritec Tanker Management

Near Miss Details

Ship File No : N/A Office File No: N/A Form No : N/A : N/A Issue : N/A Revision

: N/A

Rev Date

_				
Gu	id	a	nr	'n

01) Please do not mention any names in the near miss report.
02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet.
03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel: Asphalt Teranga Defect ID: 145

Defect Details

On 12th at 1015 HRS we received alarm from CPP (Minor clutch failure), immediately we have started Aux. Engine and took the engine on load we started the trouble shooting, all of sudden all main engine and CPP alarms were observed (Module failure, communication failure, minor/major clutch failure etc.) ,pitch became zero , and automatically ME RPM fall down (740 to 611 RPM). , the clutch got disengaged automatically and RPM was reduced to 610 from 740. The engine was restared by rectifiying the problem and command was given to bridge in 20 minutes.

Requisition Code:										
Categories										
Primary:	Near Miss		Vesse	Vessel Dept:		Deck				
Secondary :	Other	Other		Office Dept:		Technical				
Applicable Dates										
Date Raised: 12-May-2023				Date Completed :						
Other Details										
Priority :	Normal	QMS Elements Ref :			- SELECT -	Verified By :				
Show in Monthly Safety Meeting? :	No	SFI:				Verified On:				
Potential to become a serious accident : Medium					Recurrence : Low					
Causes										
Corrective Action										
Preventive Action										
Applicable Tags										
Follow Up										
On	Ву		Follow Up							
Before & After Pictures										
Before				After						

Near Miss Details Printed On: 22-May-2023 1/1