

Maritec Tanker Management

Near Miss Details

Ship File No : N/A Office File No : N/A Form No : N/A Issue : N/A Revision : N/A

: N/A

Rev Date

Guidance:

01) Please do not mention any names in the near miss report.

02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet. 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel: Asphalt Teranga Defect ID: 145

Defect Details

On 12th at 1015 HRS we received alarm from CPP (Minor clutch failure), immediately we have started Aux. Engine and took the engine on load we started the trouble shooting, all of sudden all main engine and CPP alarms were observed (Module failure, communication failure, minor/major clutch failure etc.) pitch became zero, and automatically ME RPM fall down (740 to 611 RPM)., the clutch got disengaged automatically and RPM was reduced to 610 from 740. The engine was restared by rectifiying the problem and command was given to bridge in 20 minutes.

Requisition Code:									
Categories									
Primary :	Near Miss			Vessel Dept :			Deck		
Secondary:	Other		Office De		t :	Technical			
Applicable Dates									
Date Raised: 12-May-2023					Į.	Date Completed :			
Other Details									
Priority :	Normal	Normal QMS Elements		Ref :	- 8	SELECT -	Verified By :		
Show in Monthly Safety Meeting? :	No SFI:						Verified On:		
Potential to become a serious accident : Medium					F	Recurrence : Low			
Causes									
Corrective Action									
Preventive Action									
Applicable Tags									
Follow Up									
On	Ву		Follow	w Up					
Before & After Pictures									
Before						After			

Near Miss Details Printed On: 22-May-2023 1/1