

Maritec Tanker Management Private Limited

Near Miss Details

Guidance: 01) Please do not mention any names in the near miss report. 02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet. 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.									
Vessel : Demerara	: Demerara			Defect ID : 85					
Defect Details									
Discharging sludge to barge operation. While heaving up the sludge hose, The heaving line observed to have less strenghth as it was stretched to maximum and become thin. Heaving operation was stopped immedeately but in the mean time heaving line broke and snapped, luckinly there was no one in the vicinity and henceforth a major accident was saved from occorance. Entire crew advised to check the line before using, to have sufficient strenghth in accordance with the load to be lifted. Requisition Code :									
Categories									
Primary :	Near Miss		Vessel Dept :		Engine	Engine			
Secondary :	Incorrect tools & equipment		Office Dept :		Safety				
Applicable Dates									
Date Raised : 14-Au	ıg-2023		Date Completed : 01-Sep-2023						
Other Details									
Priority :	Normal	QMS Elements Ref :		- SELECT -	Verified By :				
Show in Monthly Safety Meeting? :	No	SFI :			Verified On :				
Potential to become a	serious accio	dent : High	Recurrence : Low						
Causes									
LACK OF TRAINING FOR USING ROPES.									
Corrective Action									
All crew advised to check the rope before using, to have sufficient strenghth in accordance with the load to be lifted.									
Preventive Action									
TRAINING TO BE GIVEN FOR SAFE MOORING OPERATIONS AND USE OF ROPES FOR DIFFERENT OPERATIONS.									
CONTRIBUTING FACTORS									
Descriptions									
Others									
Root Causes- Management Factors									

Inadequate Training								
Root Causes- Personal Factor								
Lack of Knowledge								
Job Factors								
Inadequate Familiarization								
Personal Factors								
Lack of Knowledge								
Follow Up								
On	Ву	Follow Up						
Before & After Pictures								
Before			After					