



## Maritec Tanker Management

### Near Miss Details

Ship File No : N/A  
Office File No : N/A  
Form No : N/A  
Issue : N/A  
Revision : N/A  
Rev Date : N/A

**Guidance:**

- 01) Please do not mention any names in the near miss report.
- 02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet.
- 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel : Bitu Express

Defect ID : 181

**Defect Details**

During HRA transit , VSAT vessel communication system running in very poor quality.

Requisition Code :

**Categories**

Primary :	Near Miss	Vessel Dept :	Deck
Secondary :	Inadequate Engineering /Design	Office Dept :	IT

**Applicable Dates**

Date Raised : 14-Nov-2021

Date Completed : 23-Nov-2021

**Other Details**

Priority :	Urgent	QMS Elements Ref :	- SELECT -	Verified By :	Nawin Khaware
Show in Monthly Safety Meeting? :	No	SFI :		Verified On :	22/Dec/2021
Potential to become a serious accident : High			Recurrence : High		

**Causes**

Seeting Of the VSAT antenna for better coverage on vessel trading area

**Corrective Action**

Company and Provider were informed, need shore service.

**Preventive Action**

The antenna should set the elevation to a calculated value and search for satellite through 360° in azimuth.

**Applicable Tags****Descriptions**

Others

**Root Causes- Job Factor**

Inadequate Engineering

**Root Causes- Management Factors**

Inadequate Resources for Operations

**Root Causes- Personal Factor**

Inadequate Communication

**Direct Causes- Unsafe Acts**

Servicing, Equipment in Operation

**Job Factors**


Inadequate Work Standards

**Follow Up**

On	By	Follow Up	
22/Dec/2021	Nawin Khaware	lem has been repaired, hence can be considered as closed.	
23/Nov/2021	Gelu Antin   Staff Code - 10124 - MST	On this moment , working satisfactory.	<a href="#">Link1</a>
14/Nov/2021	Gelu Antin   Staff Code - 10124 - MST	All checks were done, Company was informed, VSAT antenna need to be set properly in order to have better coverage.	<a href="#">Link1</a> <a href="#">Link2</a>

**Before & After Pictures**

**Before**



**After**

