



Maritec Tanker Management

Near Miss Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Guidance:

- 01) Please do not mention any names in the near miss report.
- 02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet.
- 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel : Biskra

Defect ID : 81

Defect Details

During Loading operation (STS) from BITU ATLANTIC, minor leak found on vessels hose. At the time of Leak the Manifold pressure was zero on Biskra and 1 bar on Bitu Atlantic.

Requisition Code :

Categories

Primary :

Near Miss

Vessel Dept :

Deck

Secondary :

Other

Office Dept :

Safety

Applicable Dates

Date Raised : 15-Apr-2022

Date Completed : 26-Apr-2022

Other Details

Priority :

Normal

QMS Elements Ref :

- SELECT -

Verified By :

Nawin Khaware

Show in Monthly Safety Meeting? :

No

SFI :

Verified On :

08/Sep/2022

Potential to become a serious accident : High

Recurrence : Low

Causes

Wear and Tear

Corrective Action

Stopped Loading immediately and Disconnected the hose. Change the hose and Resumed Loading.

Preventive Action

Hoses to be pressure tested regularly and During connection laying should be proper.

Applicable Tags**Root Causes- Job Factor**

Excessive Wear and Tear

Follow Up

On	By	Follow Up	
----	----	-----------	--

26/Apr/2022	Ayaz Eqbal Upadhye Staff Code - 10346 - MST	The damaged hose is not in use anymore.	
-------------	--	---	--

Before & After Pictures

Before	After
--------	-------



